

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1531628794		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: BOPCO, L.P. 240737		Contact: Amy Ruth			
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329			
Facility Name: BEU DI-2 #2H		Facility Type: Exploration and Production			
Surface Owner: Federal		Mineral Owner: Federal		API No. 30-015-41861	

LOCATION OF RELEASE



Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	34	19S	31E	660	North	1215	East	Eddy

Latitude 32.622370° Longitude -103.852380°

NATURE OF RELEASE

Type of Release Crude Oil and Produced Water	Volume of Release 8 bbl oil 2 bbl PW	Volume Recovered 0 bbls
Source of Release Wellhead tubing	Date and Hour of Occurrence 11/5/2015 at 2 pm	Date and Hour of Discovery 11/5/2015 at 2 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A	NM OIL CONSERVATION ARTESIA DISTRICT NOV 10 2015	
Describe Cause of Problem and Remedial Action Taken.* Fluid escaped out of open tubing during work on wellhead by pulling unit. Safety valve was closed.		
RECEIVED		
Describe Area Affected and Cleanup Action Taken.* The leak misted 9,820 ft ² of caliche pad.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Amy Ruth		Approved by Environmental Specialist: 	
Title: Assistant Remediation Foreman		Approval Date: 11/10/15	Expiration Date: N/A
E-mail Address: ACRuth@basspet.com		Conditions of Approval:	
Date: 11/9/2015 Phone: 432-661-0571		Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 12/12/15	

* Attach Additional Sheets If Necessary

2RP-3383

Patterson, Heather, EMNRD

From: Ruth, Amy C. <ACRuth@BassPet.Com>
Sent: Monday, November 09, 2015 2:26 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Subject: BEU DI-2 #2H Initial C-141
Attachments: BEU DI-2 #2H Initial C-141.pdf

Hello everyone,

This leak occurred on Thursday 11/5/2015. Please call me with any questions/concerns...

Thank you!



Amy C. Ruth
BOPCO, L.P.
EH&S Remediation Specialist
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office: (575)887-7329
Fax: (575)887-7473
Cell: (432)661-0571