

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1532742191

OPERATOR <input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report	
Name of Company Devon Energy Production <u>L0137</u>	Contact Leonard Aguilar Production Assistant Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575.513.1930
Facility Name Chimayo 16 State 3	Facility Type SWD

Surface Owner State	Mineral Owner State	API No. 30-015-38105
---------------------	---------------------	----------------------

LOCATION OF RELEASE

Unit Letter F	Section 16	Township 25S	Range 29E	Feet from the 1610	North/South Line FNL	Feet from the 1455	East/West Line FWL	County EDDY
------------------	---------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	----------------

Latitude: Longitude:

NATURE OF RELEASE

Type of Release Spill Produced Water	Volume of Release 7 BBL Produced Water	Volume Recovered 7 BBL Produced Water ?
Source of Release Sump Tank	Date and Hour of Occurrence 11/18/15 at 3:00 PM	Date and Hour of Discovery 11/18/15 at 3:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD Jim Amos BLM Mike Bratcher	
By Whom? Leonard Aguilar	Date and Hour OCD 11/19/15 at 11:52 am BLM 11/19/15 at 11:55 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

NM OIL CONSERVATION
ARTESIA DISTRICT
NOV 20 2015

RECEIVED

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*

Sump tank overfilled bad check valve, bad check valve allowed produced water from the charge pump to flow back into the sump tank. Isolated the tank by closing valves upstream and downstream of sump tank.

Describe Area Affected and Cleanup Action Taken.*

7 BBL of Produced water released on a 30 x 50 area all on pad, 7 BBL of Produced water recovered. Vacuum truck was already on location. An environmental agency will be called out for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Jeanette Barron</u>	OIL CONSERVATION DIVISION	
Printed Name: <u>Jeanette Barron</u>	Approved by Environmental Specialist: <u>Hu</u>	
Title: <u>Field Admin Support</u>	Approval Date: <u>11/23/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>Jeanette.barron@dvn.com</u>	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: <u>11/20/15</u> Phone: <u>575.748.1813</u>	SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <u>12/23/15</u>	

* Attach Additional Sheets If Necessary

2RP-3412

Patterson, Heather, EMNRD

From: Barron, Jeanette <Jeanette.Barron@dvn.com>
Sent: Friday, November 20, 2015 1:14 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Cc: Fulks, Brett; Aguilar, Leonard; Garcia, Ruben
Subject: C-141 Chimayo 16 state 3
Attachments: C-141 Chimayo 16 state 3 11.18.15.doc; Chimayo 16 state 3 11.18.15.jpg; Chimayo 16 state 3.pdf

Please see attached, should you have any questions please contact Production Assistant Foreman or EHS representative Brett Fulks.

Have a great Thanksgiving!

Thanks,

Jeanette Barron
Field Admin Support-Production

Devon Energy Corporation
P.O. Box 250
Artesia, NM 88211
575 748 1813 Direct
jeanette.barron@dvn.com


devon

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.