District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

Was Immediate Notice Given?

Was a Watercourse Reached?

Lupe Carrasco

If a Watercourse was Impacted, Describe Fully.\*

By Whom?

# NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

1220 South St. Francis Dr. Santa Fe, NM 87505

State of New Mexico

**Oil Conservation Division** 

**Release Notification and Corrective Action** 

nABIS	533(3	8558		_	, OPERA	ATOR	🛛 Initi	al Report	Final Report
Name of Co	mpany: C	OG Operati	1g LLC	229/3	7   Contact: F	lobert McNeill			
Address: 60	0 West Illi	inois Avenue	, Midlan			No. 432-230-00	77		
Facility Nar	ne: COLT	STATE SW	D #004		Facility T	ype: SWD	· ·	·	
Surface Owner: State Mineral Owner				wner:	API No. 30-015-41401				
				LOCA	TION OF RI	ELEASE			
Unit Letter D	Section 5	Township 25ØS	Range 28E	Feet from the 1066	North/South Line North	Feet from the 850	East/West Line West		County Eddy
		,		Latitude 32.1	636543 Longitu	<b>de -</b> 104.1154556			
				NAT	URE OF RE	LEASE			
Type of Release:			Volume	of Release:	Volume	Volume Recovered:			
Oil & Produced Water			22 bbls (	Dil 125 bbls PW	22 bbls C	22 bbls Oil ; 124 bbls PW			
Source of Release:				Date and	Hour of Occurrent	ce: Date and	Date and Hour of Discovery:		
Tank Overflow				11/16/20	15 1:00 pm	11/16/20	11/16/2015 1:00 pm		

If YES, To Whom?

Mike Bratcher - NMOCD

Date and Hour: Tue 11/17/2015 8:46 AM

If YES, Volume Impacting the Watercourse.

Describe Cause of Problem and Remedial Action Taken.*
This release was caused when a high volume alarm malfunctioned, failing to send a notification, resulting in the tank overflowing. Vacuum trucks were
dispatched to recover the standing fluid.

Describe Area Affected and Cleanup Action Taken.\*

This release occurred within a lined facility. All fluid was able to be recovered, the facility cleaned, repaired, and put back into service.

Yes 🗌 No 🗌 Not Required

🗌 Yes 🛛 No

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	Approved by Environmental Specialist:		
Printed Name: Amanda Trujillo Davis	Approved by Environmental Specialist:	- <i>m:m</i>	
Title: Senior Environmental Coordinator	Approval Date: 1212-15 Expiration	Date: N/A	
E-mail Address: atrujillo@concho.com	Conditions of Approval:	Attached	
Date: November 30, 2015 Phone: 575-748-6940	FINAL		
* Attach Additional Sheets If Necessary		2RP-3420	

DEC 01 2015 Energy Minerals and Natural Resources

Submit L Copy to appropriate District Office in RECEIVATOR and ance with 19.15.29 NMAC.

## **Bratcher, Mike, EMNRD**

From:	Amanda Trujillo Davis <atrujillo@concho.com></atrujillo@concho.com>
Sent:	Monday, November 30, 2015 5:13 PM
To:	Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Subject:	(C-141 Initial-Final) Colt State #4 SWD (30-015-41401)
Attachments:	11-16-2015 Colt State #4 SWD (TB) Initial-Final.pdf

Mr. Bratcher,

Attached is a C-141 Initial-Final for your consideration. Please feel to contact me if you have any additional questions or concerns.

Thank you,

#### Amanda Trujillo Davis

Senior Environmental Coordinator COG Operating LLC Cell: 505.350.1336 Office: 575.748.6930 atrujillo@concho.com

1401 Commerce Drive Carlsbad, NM 88220



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

From: Lupe Carrasco
Sent: Tuesday, November 17, 2015 8:46 AM
To: 'mike.bratcher@state.nm.us'; 'Heather.Patterson@state.nm.us'
Subject: (Notification) Colt State #4 SWD (30-015-41401)

Mr. Bratcher,

COG Operating LLC is reporting a release on the Colt State #4 SWD (30-015-41401). Unit D Section 5, Township 25S Range 28E

The release occurred at 1:00 pm on 11/16/2015. Released: 22 bbls oil; 125 bbls produced water Recovered: 22 bbls oil; 125 bbls produced water

The release was due to an alarm malfunction. The area is being evaluated and a C-141 will be submitted. If you have any additional questions please feel free to contact me.

#### Thanks!

# Lupe Carrasco

Environmental Coordinator Concho Resources Cell: 575-725-0787 Office: 575-748-6933 gcarrasco@concho.com

1401 Commerce Drive Carlsbad, NM 88220



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

# Patterson, Heather, EMNRD

From:		
Sent:		
To:		
Subject:	,	

Lupe Carrasco <GCarrasco@concho.com> Tuesday, November 17, 2015 8:46 AM Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD (Notification) Colt State #4 SWD (30-015-41401)

Mr. Bratcher,

COG Operating LLC is reporting a release on the Colt State #4 SWD (30-015-41401) . Unit D Section 5, Township 25S Range 28E

The release occurred at 1:00 pm on 11/16/2015. Released: 22 bbls oil; 125 bbls produced water Recovered: 22 bbls oil; 125 bbls produced water

The release was due to an alarm malfunction. The area is being evaluated and a C-141 will be submitted. If you have any additional questions please feel free to contact me.

Thanks!

## Lupe Carrasco

Environmental Coordinator Concho Resources Cell: 575-725-0787 Office: 575-748-6933 gcarrasco@concho.com

1401 Commerce Drive Carlsbad, NM 88220



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.