

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1535131870

OPERATOR

X Initial Report ☐ Final Report

Name of Company Tandem Energy Corporation	Contact Darrell Finney
Address P.O. Box 1559, Midland Texas 79705	Telephone No. 575-365-5639
Facility Name Southland State No.2	

Surface Owner State	Mineral Owner State	API No. 30-015-25212
---------------------	---------------------	----------------------

LOCATION OF RELEASE

Unit Letter B	Section 7	Township 19S	Range 28E	Feet from the 330'	North/South Line North	Feet from the 2310'	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	----------------

Latitude 32.32.68113 Longitude 104.21329

NATURE OF RELEASE

Type of Release Oil	Volume of Release 20 bbl.	Volume Recovered 0
Source of Release Gun Barrel	Date and Hour of Occurrence	Date and Hour of Discovery 12/15/2015 12:30 pm
Was Immediate Notice n? X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Randy Dade	
By Whom? Darrell Finney	Date and Hour 12/15/2015 12:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

High wind damaged the water leg attached to the gun barrel causing a release of 20 bbl. oil, the impacted area was the bermed area of the tank battery, the impacted area located outside of the bermed area was measured to be 3'-21' wide x 105' Long. R.T. Hicks Consultants has been contacted to construct a Remediation plan and corrective actions for the release.



NM OIL CONSERVATION  
ARTESIA DISTRICT

Describe Area Affected and Cleanup Action Taken.\*

DEC 16 2015

RECEIVED

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Darrell Finney	Signed By  Approved by Environmental Specialist:	
Title: Agent for Tandem Energy Corporation	Approval Date: 12/17/15	Expiration Date: N/A
E-mail Address: darrellfinney@yahoo.com	Conditions of Approval: C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 12/16/2015 Phone: 575-365-5639	SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 11/17/16	

\* Attach Additional Sheets If Necessary

200-3457