

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

FAB1535241846 **Release Notification and Corrective Action**
NAB1535242436 **281788 OPERATOR** Initial Report Final Report

Name of Company: Apache Corporation	Contact Bruce Baker
Address: 2350 W Marland Blvd Hobbs, NM 88240	Telephone No. (432) 631-6982
Facility Name Loco Hills SWD Booster Station	Facility Type: Booster Station

Surface Owner BLM	Mineral Owner	API No.
-------------------	---------------	---------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from t	East/West Line	County
G	24	17S	30E					Eddy

Latitude N32.8227272 Longitude W103.9233551

NATURE OF RELEASE

Type of Release: Oil and produced water	Volume of Release 1895 barrels of produced water and 25 barrels of oil.	Volume Recovered 1890 barrels of produced water and 25 barrels of oil.
Source of Release: PVC water boot	Date and Hour of Occurrence 11/21/2015	Date and Hour of Discovery 11/21/2015
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher (NMOCD) Shelly Tucker (BLM)	
By Whom? Bruce Baker	Date and Hour 11/22/2015 via email at 9:37 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION
ARTESIA DISTRICT
DEC 17 2015
RECEIVED

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Due to high winds a 6 inch PVC water boot sheared off between two 1,000 barrel tanks resulting in the loss of fluid. The power was shut off to transfer pump and the two 6 inch valves were closed on the tanks. The connections to the boot were replaced with metal connections.

Describe Area Affected and Cleanup Action Taken.*
The majority of the release was contained inside the lined facility. However the containment was breached on the Northwest corner resulting in loss of fluid in pasture and on lease pad. A vacuum truck was dispatched to pick-up fluid. The area was mapped.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bruce Baker</i>	OIL CONSERVATION DIVISION	
Printed Name: Bruce Baker	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Environmental Technician	Approval Date: 12/18/15	Expiration Date: N/A
E-mail Address: larry.baker@apachecorp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/18/2015 Phone: (432) 631-6982	Remediation per O.C.D. Rules & Guidelines	

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 1/18/16 **2RP-3460**

Patterson, Heather, EMNRD

From: Baker, Larry <Larry.Baker@apachecorp.com>
Sent: Friday, December 18, 2015 9:16 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov
Subject: Loco Hills SWD Booster Station
Attachments: Loco Hills SWD Booster Station Initial C-141.pdf

All,

Attached is the initial C-141 for the above referenced site. Please let me know if you have any questions or wish to discuss. Thanks and have a good day.

Bruce Baker
Apache Corporation
Environmental Technician
Northwest District
Email: larry.baker@apachecorp.com
Mobile: 432-631-6982