

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1535753747		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: BOPCO, L.P.		260737			
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Contact: Bradley Blevins			
Facility Name: PLU 232		Telephone No. 575-887-7329			
		Facility Type: Exploration and Production			
Surface Owner: State		Mineral Owner:		API No. 3001534009	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	31	24S	30E	990		990		Eddy

Latitude: 32.178226 Longitude: 103.925705

NATURE OF RELEASE

Type of Release: Crude oil, Produced Water	Volume of Release: 3 barrels oil, 4 barrels PW	Volume Recovered: None
Source of Release: Stuffing Box	Date and Hour of Occurrence: 12-17-15 @ 8:00am	Date and Hour of Discovery: 12-17-15 @ 8:30am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION  
ARTESIA DISTRICT

DEC 22 2015

RECEIVED

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
BOPCO EHS was notified of a release that occurred when the packing in the stuffing box failed causing oil and produced water to be released to the well pad.

Describe Area Affected and Cleanup Action Taken.\*  
A vacuum truck was called to the location; by the time the vacuum truck arrived the fluid had already soaked into the soil. A backhoe was used to remove the heavy saturated material from the well pad; the material was hauled to Lea Land for disposal. Samples were collected from the release area and will be discussed with OCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Bradley Blevins</u>		OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins		Approved by Environmental Specialist: <u>[Signature]</u>	
Title: Assistant Remediation Foreman		Approval Date: <u>12/23/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: bblevins@basspet.com		Conditions of Approval:	
Date: <u>12-22-15</u> Phone: 432-214-3704		Remediation per O.C.D. Rules & Guidelines	
		SUBMIT REMEDIATION PROPOSAL NO	
		LATER THAN: <u>1/24/16</u>	

\* Attach Additional Sheets If Necessary

2RP-3463

**Patterson, Heather, EMNRD**

---

**From:** Blevins, Bradley <BBlevins@BassPet.Com>  
**Sent:** Tuesday, December 22, 2015 10:35 AM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD  
**Cc:** Amos, James; Blevins, Bradley  
**Subject:** Initial C-141 PLU 232  
**Attachments:** Initial C-141 PLU 232.pdf

All,

Please find the attached initial C-141 for the release that occurred at the PLU 232 location, if you have any questions please let me know.

Thank you,

Brad Blevins  
Remediation Foreman  
BOPCO, LP  
522 W. Mermod, Suite 704  
Carlsbad, NM 88220  
Office-575-887-7329  
Cell-1-432-214-3704  
bblevins@basspet.com