

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT Form C-141
Revised August 8, 2011
JAN 06 2015
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB11001139679 *60137* OPERATOR Initial Report Final Report

Name of Company Devon Energy Production Company	Contact Rudy Zuniga Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-390-5435
Facility Name Diamond PWU 22 #1H	Facility Type Oil
Surface Owner State	Mineral Owner State
API No 30-015-38334	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	22	19S	29E	575	North	330	West	Eddy

Latitude: N 32°65'19.52"

Longitude: W 104°07'01.29"

NATURE OF RELEASE

Type of Release Spill Oil	Volume of Release .5 bbl oil	Volume Recovered .0 bbl
Source of Release 2 phase separator dump valve	Date and Hour of Occurrence 12.23.15 @ 11:30 am	Date and Hour of Discovery 12.23.15 @ 11:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson @ OCD	
By Whom? Jesse Armendariz Assistant Production Foreman	Date and Hour 12.23.15 @ 11:40 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
2 phase separator dump valve was stuck causing a .5 bbl oil spray release. Well was shut in to prevent further release. The dump valve was rebuilt.

Describe Area Affected and Cleanup Action Taken.*
.5 bbl oil spray was released on the East, South East side of the pad. None of the spray was recovered. The size of the affected area was 10'x20' off the pad. Environmental agency to be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Corina Moya</i>	OIL CONSERVATION DIVISION	
Printed Name: Corina Moya	Signed By <i>White</i>	
Title: Field Admin Support	Approved by Environmental Specialist:	Approval Date: <i>1/11/16</i> Expiration Date: <i>N/A</i>
E-mail Address: <i>corina.moya@dvn.com</i>	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 1.5.16 Phone: 575.746.5559	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: *1/11/16* **2RP-3482**

Bratcher, Mike, EMNRD

From: Moya, Corina <Corina.Moya@dvn.com>
Sent: Wednesday, January 06, 2016 9:33 AM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Subject: Diamond PWU 22 #1H_5 bbl oil off pad 12.23.15
Attachments: Diamond PWU 22_1H .5 bbl oil spray 12.23.15 pic 1 of 2.JPG; Diamond PWU 22_1H .5 bbl oil spray 12.23.15 pic 2 of 2.JPG; Diamond PWU 22_1H .5 bbl oil spray 12.23.15 C-141.doc; Diamond PWU 22_1H .5 bbl oil spray 12.23.15 GIS Mapping.pdf

Good morning,
Please see the attached information for the Diamond PWU 22 #1H .5 bbl oil spill on 12.23.15

Thank you,

Corina Moya
Field Admin Support
Production
B Schedule

Devon Energy Corporation
PO Box 250
Artesia, NM 88211
575 746 5559



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.