


Excavation Map

Final Laboratory Sampling

	CI-	GRO	DRO
Pasture 5 pt Comp. @ 6"	52	<4	<50
Pasture North Wall	9	<4	<50
Pasture South Wall	24	<4	<50
Pasture West Wall	28	<4	<50
Pad 5 pt Comp @ 2'	90	<4	<50
Pad North Wall	57	<4	<50
Pad East Wall	100	<4	<50
Pad West Wall	109	<20	<50



Legend


- | | | | |
|--|------------------------|--|--------------------------|
| | DEADMAN | | OVERHEAD ELECTRICAL LINE |
| | ELECTRIC POLE | | PAD |
| | CONTROL BOX | | SURFACE PIPELINE |
| | ELECTRICAL BOX | | SCRAPE (6") |
| | WELLHEAD | | PUMP JACK |
| | BURIED ELECTRICAL LINE | | STAIN (3501 sq ft TOTAL) |

Landowner = Bunin, NB Properties DGW = 41 ft



**APACHE
BUNIN #006**

LEGALS: UL/A Sec. 13
T21S - R37E
LEA COUNTY, NM




GPS date: 7/9/2013 EC
Drawing date: 8/1/13
Drafted by: L. Weinheimer

30-02539547

Final Samples (7-12-13)kl

Sample Description	Water	Soil	AGNO3	Cl-	PID	
<u>pasture</u>						
composite	30.3	10.4	2.91	0.06	175	15.3
<u>walls</u>						
<u>north wall</u>						
point 1	30.3	10.8	2.81	0.05	140	0.8
point 2	31	10.4	2.98	0.05	149	0
point 3	30.2	10.5	2.88	0.05	144	2
<u>south wall</u>						
point 1	30.6	10.5	2.91	0.04	117	
point 2	30.2	10.7	2.82	0.04	113	1.2
point 3	30.7	10.5	2.92	0.05	146	
<u>west wall</u>						
point 1	30.1	10.8	2.79	0.05	139	0.4
<u>pad</u>						
composite	30.6	10.4	2.94	0.07	206	0.4
<u>walls</u>						
<u>east wall</u>						
point 1	30.9	10.3	3.00	0.06	180	0.3
point 2	30.6	10.6	2.89	0.08	231	1.1
point 3	30.4	10.9	2.79	0.07	195	0.1
<u>west wall</u>						
point 1	30.1	10.1	2.98	0.07	209	0.1
point 2	31.1	10.3	3.02	0.06	181	2.5
point 3	30.4	10.5	2.90	0.08	232	0.6
north wall	30.2	10.9	2.77	0.07	194	0.3

Initial Sampling Data



APACHE BUNIN #006

LEGALS: UL/A Sec. 13
T21S - R37E
LEA COUNTY, NM



0 50 100
Feet


GPS date: 7/3/2013 KS
Drawing date: 7/16/2013
Drafted by: L. Weinheimer

Final Samples (7-12-13)kl

Sample Description	Water	Soil	AGNO3	Cl-	PID	
<u>pasture</u>						
composite	30.3	10.4	2.91	0.06	175	15.3
<u>walls</u>						
<u>north wall</u>						
point 1	30.3	10.8	2.81	0.05	140	0.8
point 2	31	10.4	2.98	0.05	149	0
point 3	30.2	10.5	2.88	0.05	144	2
<u>south wall</u>						
point 1	30.6	10.5	2.91	0.04	117	
point 2	30.2	10.7	2.82	0.04	113	1.2
point 3	30.7	10.5	2.92	0.05	146	
<u>west wall</u>						
point 1	30.1	10.8	2.79	0.05	139	0.4
<u>pad</u>						
composite	30.6	10.4	2.94	0.07	206	0.4
<u>walls</u>						
<u>east wall</u>						
point 1	30.9	10.3	3.00	0.06	180	0.3
point 2	30.6	10.6	2.89	0.08	231	1.1
point 3	30.4	10.9	2.79	0.07	195	0.1
<u>west wall</u>						
point 1	30.1	10.1	2.98	0.07	209	0.1
point 2	31.1	10.3	3.02	0.06	181	2.5
point 3	30.4	10.5	2.90	0.08	232	0.6
north wall	30.2	10.9	2.77	0.07	194	0.3


Apache Bunin #006 AD

Unit Letter A, Section 13, T21S, R37E




Initial release area, facing south

7/3/13




Initial release area, facing north

7/3/13




Initial release area, facing west

7/3/13



Initial release area, facing southwest

7/3/13



Collecting samples, facing north

7/3/13




Excavating on the pad, facing south

7/9/13




Excavating in the pasture, facing east

7/9/13



Importing soil, facing southwest

7/9/13




Exporting soil, facing north

7/12/13




Final excavation in pasture, facing west

7/12/13



Final excavation in pasture, facing east

7/12/13



Final excavation in pad, facing north

7/12/13