

76District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NABILED2552306		OPERATOR		<input type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company BOPCO, L.P.		2100737		Contact	
Address P.O. Box 2760, Midland Texas 79702				Telephone No. 432-683-2277	
Facility Name Poker Lake Unit 457H/421H Dual Well Pad				Facility Type: Drilling Location	
Surface Owner		Mineral Owner		API No. 30-015-42112	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	27	25S	30E	560	SOUTH	950	EAST	EDDY

Latitude 32.095258 Longitude -103.863036

NATURE OF RELEASE

Type of Release Contaminated soil	Volume of Release	Volume Recovered
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Describe Area Affected and Cleanup Action Taken.*


48 yards of contaminated soil following drilling location cleanup was hauled to CRI 4/11/2014.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: TASHA SPORT		OIL CONSERVATION DIVISION	
Printed Name: Tasha Sport		Accepted for record	
Title: Regulatory Compliance Manager		Approved by Environmental Specialist: NMOCD	
E-mail Address: Tasha@sportenvironmental.com		Approval Date: 1/25/16	Expiration Date: N/A
Date: 5/9/2014 Phone: 432-683-1100		Conditions of Approval: FINAL	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2EP-3513






SPORT ENVIRONMENTAL SERVICES, PLLC

502 N. Big Spring Street, Midland, Texas 79701

Business: 432.683.1100 Fax: 888.500.0622

May 13, 2014

Mr. Mike Bratcher
State of New Mexico
Oil Conservation Division
811 S. First Street
Artesia, NM 88210



Re: **Closed-Loop System Closure Report**
BOPCO, L.P., Poker Lake Unit #457H
Section 27, T-25-S, R-30-E
Eddy County, New Mexico

Dear Mr. Bratcher,

On behalf of BOPCO, L.P., Sport Environmental Services is providing the enclosed NMOCD Release Notification and Corrective Action, Form C-141 for BOPCO, L.P.'s Poker Lake Unit #457H location.

Following casement of drilling operations, restoration of the impacted area involved, blading and smoothing out the location. Site closure consisted of removing visual signs of contaminated soil and restoring the impacted area with reclaimed caliche. Approximately 48 cubic yards of visually impacted soil was excavated and disposed of offsite at the NMOCD permitted and approved facility, Lea Land, Inc Landfill. (Permit #WM-1-035). Caliche from the edge of the location was used as backfill.

The Poker Lake Unit #421H well and Poker Lake Unit #457H well were located on a dual well pad. A C-144 Closed Loop System Closure report was submitted for the Poker Lake Unit #421H location, as it was permitted prior to the pit rule change.

If you have any questions or comments with regard to this matter, please contact me at my office (432.683.1100). I would be more than happy to review this closure report with you.

Sincerely,

Tasha Sport

Regulatory Compliance Manager

Enclosures: NMOCD Form C-141 (Release Notification and Corrective Action)