NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

JAN 2 6 2016

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Reprint Copy to appropriate District Office in the cordance with 19.15.29 NMAC.

OPERATOR	_			Rele	ase Notific	atio	n and Co	rrective A	ction	l				
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 Telephone No. 575-887-7329 Facility Name: North Indian Flats 24 Federal #015 Surface Owner: Federal Mineral Owner: Federal	NAK	1402	OPERATOR Initial Report Final F						Final Report					
Surface Owner: Federal				/	240737		Contact: Amy Ruth							
Surface Owner: Federal														
Unit Letter Section 24 21S Range 28E 330 North/South Line 660 West County Eddy Latitude 32.472117º Longitude 104.046462º NATURE OF RELEASE NATURE OF RELEASE NATURE OF RELEASE Type of Release Crude Oil Volume of Release 5 bbls Volume Recovered 3 bbls Source of Release Suffing Box Date and Hour of Occurrence Date and Hour of Discovery 1/13/2016 time unknown 1/13/2016 to am 1/1	Facility Name: North Indian Flats 24 Federal #015							Facility Type: Exploration and Production						
Latitude 24 21S 28E 330 North/South Line Feet from the Morth/South Line Feet from the G60 Morth Eddy	Surface Owner: Federal Mineral Owner:							Federal API No.				9137		
Latitude 24 21S 28E 330 North/South Line Feet from the Morth/South Line Feet from the G60 Morth Eddy	LOCATION OF RELEASE													
Latitude 32.472117° Longitude -104.046462° NATURE OF RELEASE Volume Recovered 3 bbls Volume Recovered 3 bbls Source of Release Suffing Box Date and Hour of Occurrence Date and Flour of Discovery	Unit Letter	Section	Township	Range				Vest Line	County					
Type of Release	D	24	215	28E	330	North		660	West		Eddy			
Type of Release								10404545			l			
Type of Release Crude Oil Source of Release Stuffing Box Date and Hour of Occurrence 1/13/2016 time unknown 1/13														
Source of Release Stuffing Box Date and Hour of Occurrence M13/2016 time unknown If YES, To Whom? N/A Date and Hour N/A By Whom? N/A Date and Hour N/A Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. N/A Describe Cause of Problem and Remedial Action Taken.* Stuffing box packing on the well head failed. The e-pot on the pumping unit shut down the well and the packing was replaced. Describe Area Affected and Cleanup Action Taken.* The leak affected 1284 ft² of well pad and vacuum trucks recovered standing fluids. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed Loadequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or loopflawd and/or regulations. OIL CONSERVATION DIVISION Signature Approved by Environmental Specialist Approval Date: 22/116/6 Expiration Date: Attached Remediation per O.C.D. Rules & Guidellines														
Was Immediate Notice Given? Yes No Not Required N/A Date and Hour N/A If YES, Volume Impacting the Watercourse. N/A Describe Cause of Problem and Remedial Action Taken.* Stuffing box packing on the well head failed. The e-pot on the pumping unit shut down the well and the packing was replaced. Describe Area Affected and Cleanup Action Taken.* The leak affected 1284 ft² of well pad and vacuum trucks recovered standing fluids. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or flic certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or locatinawa and/or regulations. OIL CONSERVATION DIVISION Signature Printed James Acruth@basspet.com Approved by Environmental Specialist Approved by Environmental Square Conditions of Approval: Remediation per O.C.D. Rules & Guidblines														
By Whom? N/A Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. N/A If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* Stuffing box packing on the well head failed. The e-pot on the pumping unit shut down the well and the packing was replaced. Describe Area Affected and Cleanup Action Taken.* The leak affected 1284 ft² of well pad and vacuum trucks recovered standing fluids. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In address investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. The acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature Approved by Environmental Specialist Approved by Environmental Specialist Approval Date: 26 6 6 7 7 7 7 7 7 7	Source of Release Stuffing Box													
By Whom? N/A Was a Watercourse Reached? Yes No If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* Stuffing box packing on the well head failed. The e-pot on the pumping unit shut down the well and the packing was replaced. Describe Area Affected and Cleanup Action Taken.* The leak affected 1284 ft° of well pad and vacuum trucks recovered standing fluids. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a "Final Report" does not relieve the operator of responsibility for compliance with any other federal, state, or locaflaws and/or regulations. OIL CONSERVATION DIVISION Signature Approved by Environmental Specialist.								If YES, To Whom?						
Was a Watercourse Reached? Yes No If YES, Volume Impacting the Watercourse. N/A If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* Stuffing box packing on the well head failed. The e-pot on the pumping unit shut down the well and the packing was replaced. Describe Area Affected and Cleanup Action Taken.* The leak affected 1284 ft² of well pad and vacuum trucks recovered standing fluids. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or locations and perform corrective actions for releases which may endanger public health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or locations and perform corrective actions for releases which may endanger public health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or locations and perform corrective actions for releases which may endanger public health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or locations and performent page and the packing was replaced.	-													
If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* Stuffing box packing on the well head failed. The e-pot on the pumping unit shut down the well and the packing was replaced. Describe Area Affected and Cleanup Action Taken.* The leak affected 1284 ft² of well pad and vacuum trucks recovered standing fluids. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of intelleve the operator of intelleve the operator of releve the operator of responsibility for compliance with any other federal, state, or locaflaw and/or regulations. OIL CONSERVATION DIVISION Signature Printed James: Amy Ruth Approved by Environmental Specialist Approved by Environmental Specialist Approved Date: 24 6 Expiration Date: Attached Remediation per O.C.D. Rules & Guidplines														
Describe Cause of Problem and Remedial Action Taken.* Stuffing box packing on the well head failed. The e-pot on the pumping unit shut down the well and the packing was replaced. Describe Area Affected and Cleanup Action Taken.* The leak affected 1284 ft² of well pad and vacuum trucks recovered standing fluids. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or locaffawa and/or regulations. OIL CONSERVATION DIVISION Signature Approved by Environmenta Specialist Appr								- 1						
Describe Cause of Problem and Remedial Action Taken.* Stuffing box packing on the well head failed. The e-pot on the pumping unit shut down the well and the packing was replaced. Describe Area Affected and Cleanup Action Taken.* The leak affected 1284 ft² of well pad and vacuum trucks recovered standing fluids. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or locaffawa and/or regulations. OIL CONSERVATION DIVISION Signature Approved by Environmenta Specialist Appr														
Describe Area Affected and Cleanup Action Taken.* The leak affected 1284 ft² of well pad and vacuum trucks recovered standing fluids. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or locaflawt and/or regulations. OIL CONSERVATION DIVISION Signature Approved by Environmentar Specialist E-mail Address: ACRuth@basspet.com Conditions of Approval: Remediation per O.C.D. Rules & Guidalines	· · ·													
The leak affected 1284 ft² of well pad and vacuum trucks recovered standing fluids. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Approved by Environmental Specialist Approval Date: 26/16 Expiration Date:	Stuffing box packing on the well head failed. The e-pot on the pumping unit shut down the well and the packing was replaced.													
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local law and/or regulations. OIL CONSERVATION DIVISION Approved by Environmental Specialist: Ap														
Printed Pame: Amy Ruth Approved by Environmental Specialist: Approved by Environmental Specialist: Approved by Environmental Specialist: E-mail Address: ACRuth@basspet.com Conditions of Approval: Remediation per O.C.D. Rules & Guidelines	regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or locallaw and/or regulations.													
E-mail Address: ACRuth@basspet.com Conditions of Approval: Remediation per O.C.D. Rules & Guidelines								all 1						
E-mail Address: ACRuth@basspet.com Conditions of Approval: Remediation per O.C.D. Rules & Guidelines	Title: EHS Remediation Specialist							Approval Date: 12616 Expiration Date: N/A						
Attach Additional Sheets If Necessary SUBMIT REMEDIATION PROPOSAL NO							I Auschen I I							
4 NAME OF THE PARTY OF THE PART					61-0571		SUBMIT REMEDIATION PROPOSAL NO 2 PD-3518							

Bratcher, Mike, EMNRD

From: Ruth, Amy C. <ACRuth@BassPet.Com>

Sent: Tuesday, January 26, 2016 11:04 AM

To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD

Cc: jamos@blm.gov

Subject: North Indian Flats 24 Federal #15 C-141 for leak on 1-13-16 **Attachments:** Initial C-141 NIF 24 Federal #15 1-13-16.pdf; DSCF3993.JPG

Hello Everyone,

Please find attached, the initial form C-141 for a well head leak that occurred on 1-13-16. Don't hesitate to call me with any questions/concerns. Thank you!!



Amy C. Ruth
BOPCO, L.P.
EH&S Remediation Specialist
522 W. Mermod, Suite 704
Carlsbad, NM 88220

Office: (575)887-7329 Fax: (575)887-7473 Cell: (432)661-0571