



AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pKJ1604043200

1RP - 3067

APACHE CORP

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED

AUG 04 2010

HOBBSUCD

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Apache Corporation	Contact	Natalie Gladden
Address	PO Box 1849, Eunice NM 88231	Telephone No.	575-390-4186
Facility Name	Maxwell #1	Facility Type	Producer

Surface Owner	Deck Estate	Mineral Owner	NMOCD	Lease No.	30-025-08921
---------------	-------------	---------------	-------	-----------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	16	22S	36E	660'	FNL	1980'	FWL	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced water/skim of oil	Volume of Release 7-8bbls	Volume Recovered None
Source of Release Stuffing box leak	Date and Hour of Occurrence 06/28/2010 134pm	Date and Hour of Discovery 06/28/2010 134pm
Was Immediate Notice Given? <div><input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required</div>	If YES, To Whom? Larry Johnson	
By Whom? Natalie Gladden	Date and Hour 06/28/2010 315pm	
Was a Watercourse Reached? <div><input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</div>	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

WATER @ 210'



Describe Cause of Problem and Remedial Action Taken.*

Saturated soil was excavated immediately due to most of the fluid had soaked into the ground, large rain event was headed our way. The soil was excavated and hauled to Sundance Services.

Describe Area Affected and Cleanup Action Taken.*

Remediation will cease once the NMOCD Rules and Guidelines are followed to closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION 		
Printed Name: Natalie Gladden	Approved by District Supervisor: Environmental Specialist		
Title: EHS Environmental Tech	Approval Date: 08/04/10	Expiration Date: 10/04/10	
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval: SUBMIT FINAL C-141 BY 10/04/10		Attached <input type="checkbox"/>
Date: 07/10/2010 Phone: 575-390-4186	IRP-06-14-3067		

* Attach Additional Sheets If Necessary