

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

JAN 20 2010

HOBOCD

ppac 713431734

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Endeavor Energy Resources, LP	Contact	Alin Richardson
Address	110 N. Marienfeld, Suite 200	Telephone No.	(432) 848-0301
Facility Name	Terra Federal #1	Facility Type	Well location

Surface Owner	George Willis	Mineral Owner	George Willis	Lease No.	30-025-27245
---------------	---------------	---------------	---------------	-----------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	1/4 22 SE	25S	37E	1884'	South	2175'	West	Lea

Latitude: 32 06'49.3" Longitude: 103 09'07.7"

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	120 BBL	Volume Recovered
Source of Release	Valve Leak	Date and Hour of Occurrence:	3/25/2007	Date and Hour of Discovery
Was Immediate Notice Given?		3/25/2007 at 15:30		
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required		If YES, To Whom?		
		Endeavor Energy company representative		
By Whom? The rancher		Date and Hour 3/25/2007 at 15:30		
Was a Watercourse Reached?		If YES, Volume Impacting the Watercourse.		
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Rancher's livestock tripped open a valve causing 120 BBL leak onto surrounding areas. Landowner discovered the leak and contacted a company representative.

Describe Area Affected and Cleanup Action Taken.\*

The area affected was approximately 173'x 204'. Approximately 3,921 cubic yards of impacted soil was excavated and processed through a shredder with fertilizer. Confirmation sampling took place to ensure there was no impacted soil left in place. Confirmation samples were analyzed for Chlorides using EPA Method 4500-Cl-B and TPH using EPA Method SW-846-8015M. All backfilled soil was appropriate soil, clean and compacted. Re-vegetation took place with a minimum of 70% native perennial vegetative cover consisting of at least 3 native plant species, including at least one grass, and no noxious weeds.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of liability under federal, state, or local laws and/or regulations.

Signature: <u>Ronnie Nickell</u>	APPROVED	
Printed Name: <u>Bonnie Nickell</u>		
Title: <u>Environmental Project Manager</u>	Approval Date: <u>2/5/10</u>	Expiration Date:
E-mail Address: <u>ronnie@southenv.com</u>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <u>1-19-10</u> Phone: <u>432-425-8454</u>		

\* Attach Additional Sheets If Necessary

188 1305



District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Endeavor Energy	Contact: Alin Richardson
Address: 110 N. Marienfeld, Ste. 200 Midland, TX 79701	Telephone No.: (432) 848-0301
Facility Name: Terra Federal #1	Facility Type: Well location

Surface Owner: George Willis	Mineral Owner: George Willis	Lease No.: Terra Federal # 1
------------------------------	------------------------------	------------------------------

LOCATION OF RELEASE

Unit Letter K	Section ¼ 22 SE	Township 25S	Range 37 E	Feet from the 1884'	North/South Line South	Feet from the 2175'	East/West Line West	County Lea
------------------	-----------------------	-----------------	---------------	------------------------	---------------------------	------------------------	------------------------	---------------

Latitude: 32 06'49.3" Longitude: 103 09'07.7"

NATURE OF RELEASE

API# 30025272450000

Type of Release: Crude Oil	Volume of Release: 120 BBL	Volume Recovered:
Source of Release: Valve Leak	Date and Hour of Occurrence: 3/25/2007	Date and Hour of Discovery: 3/25/2007 at 15:30.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Endeavor Energy company representative.	
By Whom? The rancher	Date and Hour: 3/25/2007 at 15:30.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Rancher's livestock tripped valve open causing 120 BBL to leak onto surrounding areas. Land owner discovered and contacted company representative.

Describe Area Affected and Cleanup Action Taken.\*

The affected area was approximately 173' x 204'. See attached dimension and depth maps. All impacted soil was excavated. Contaminated soil was placed onto temporary containment. Bottom hole samples will be collected. The soil will be blended on site and sampled to maintain levels below 100 ppm. The remediated soil will be placed back into the excavation site.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Dennis Melton</u>	OIL CONSERVATION DIVISION	
Printed Name: Dennis Melton	Approved by District Supervisor: <u>ENRERO ENRERO</u>	
Title: Junior Project Manager	Approval Date: <u>5-11-07</u>	Expiration Date: <u>7-11-07</u>
E-mail Address: bubbamelt@grandecom.net	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4/26/2007 Phone: (432) 561-5168	Notice of Decision (NOD) PRIOR TO FINAL STOPPING	

\* Attach Additional Sheets If Necessary

incident - n PAC 0713431640  
application - p PAC 0713431734

② Submit Final C-141 w/  
Documentation

RP# 1305



# SOUTH ENVIRONMENTAL SERVICES, INC.

P.O BOX 11064  
MIDLAND, TEXAS 79702  
OFFICE: (432) 682-3547  
FAX: (432) 682-4182

January 19, 2010

Geoffrey Leking  
New Mexico Oil Conservation Division  
1625 N. French Drive  
Hobbs, NM 88240

**RECEIVED**

JAN 20 2010  
**HOBBSOCD**

Mr. Leking:

Can you please send me an email or fax with your signature on the final C-141. If you have any questions or concerns please feel free to give me a call.

Thank you,

Kristi Brunette  
Environmental Project Manager  
kristi\_brunette@yahoo.com  
432-599-9384