




AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pJXK1604731687

1RP - 2732

BURGUNDY OIL & GAS OF N M INC

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Burgundy Oil & Gas of NM, Inc.	Contact	Ben Taylor
Address	401 W. Texas, Suite 1003, Midland, TX 79701	Telephone No.	(432) 684-4033
Facility Name	State Vacuum Unit Well No. 18	Facility Type	Oil & Gas

Surface Owner:	State	Mineral Owner:	State	Lease No.	002360
----------------	-------	----------------	-------	-----------	--------

LOCATION OF RELEASE

API # 30-025-02179-00-00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	32	17S	34E	990'	South	2310'	West	Lea

Latitude N 32.78822° Longitude W 103.58448°

NATURE OF RELEASE


Type of Release	Oil & Water	Volume of Release	Unknown	Volume Recovered	None
Source of Release	Flowline	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	7/20/10
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*
HOBBS OGD
JUL 14 2011

Describe Cause of Problem and Remedial Action Taken.*
Flowline leaks on two consecutive days in 3 areas. Flowline to State Vacuum Unit No. 18 has been replaced in those affected areas. **RECEIVED**

Describe Area Affected and Cleanup Action Taken.*
Soil was excavated in two (2) separate areas: approximately 100' x 30' x 5' (deep) to the north, and approximately 170' x 130' x 3' to the south, until laboratory results of samples reported TPH concentrations below 5,000 mg/kg and chloride concentrations below 1,000 mg/kg. Impacted soil was hauled to an NMOCD approved disposal facility. The excavation to the north was backfilled with clean soil. The excavation to the south was lined with 20 mil plastic (cushioned with sand on both sides) and backfilled. A site drawing with sample locations is attached, along with laboratory documentation and a table summarizing the sample results. The area will be re-seeded with BLM #2 mixture.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Ben Taylor	Approved by ^{ENV. ENGINEER} District Supervisor: 		
Title: Production Manager	Approval Date: 08/12/11	Expiration Date: —	
E-mail Address: btaylor@t3wireless.com	Conditions of Approval: —		Attached <input type="checkbox"/>
Date: 7/8/11 Phone: (432) 684-4033	LRP-8-11-2732		

* Attach Additional Sheets If Necessary