

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

MAR 30 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB1609149408

OPERATOR

Initial Report Final Report

Name of Company: Mewbourne Oil Company <i>14744</i>	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905
Facility Name: Layla 27 SWD #1	Facility Type: SWD
Surface Owner: Private	Mineral Owner: Fee
API No. 30-015-22638	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	27	23S	28E	1980'	North	990'	East	Eddy

Latitude 32.278038 Longitude -104.0698242

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: Estimated 80 bbls.	Volume Recovered: PW (80 bbls)
Source of Release: Injection pump inlet	Date and Hour of Occurrence: 3-27-16	Date and Hour of Discovery: 3-27-16 10:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Flange failure on inlet of injection pump.		
Describe Area Affected and Cleanup Action Taken.* Affected area- Well pad surface East of tanks. Vacuum trucks were used to recover 80 bbls of produced water. Final remediation will be conducted in accordance with the NMOCD's Guidelines for Remediation of Spills, Leaks and Releases.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Z. Thomas</i>	OIL CONSERVATION DIVISION	
Printed Name: Zack Thomas	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Environmental Rep.	Approval Date: <i>3/31/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: zthomas@mewbourne.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3-30-16	Phone: 575-602-2188	


Remediation per O.C.D. Rules & Guidelines
SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 4/1/2016 *2RD 3626*

Patterson, Heather, EMNRD

From: Zack Thomas <zthomas@mewbourne.com>
Sent: Wednesday, March 30, 2016 9:33 AM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Subject: Layla 27 SWD #1
Attachments: C141- Layla 27 SWD #1 (3-27-16) MOC signed initial.pdf

Heather,

Attached is a C-141 for the Layla 27 SWD #1. This release happened over the weekend and I was out of town or I would have notified you sooner. As soon as I get a work plan together I will send it to you for approval. If there are any questions or concerns let me know. Thanks



Zack Thomas
Environmental Rep.
Mewbourne Oil Company
PO Box 5270
Hobbs, NM 88241 US

Phone: (575) 393-5905 | Fax: (575) 397-6252
(575) 602-2188
Email: zthomas@mewbourne.com



MEWBOURNE
OIL COMPANY