District I
1625 N. French Dr., Hobbs, NM 88240
District If
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rto Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

			Relea	ase Notificat	tion and Cori	rective Actio	11		
					OPERATO	R	Initial Repo	ort 🔯 Final Report	
Name of Co	mpany: C	hesapeake E	nergy Co	rp.	Contact: Brad	iev Bievins			
Address: 16						Telephone No.1 (575) 441-0341			
						Facility Type: Waste Disposal			
	. : .								
Surface Owner: BLM Mineral Owner					mer: Unknown	Unknown Lease No.: #160957			
LOCATION OF RELEASE									
Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County	
NW/4 of NE/4	11	245	31E	660	FNL	1980'	FEL	Eddy	
Latitude: N32° 14' 14.83" Longitude: W103° 44' 46.89"									
NATURE OF RELEASE									
Type of Rele						ne of Release: 300 bbis Volume Recovered: 242 bbis			
Source of Re	lease: Equi	pment Fallure			July 11, 2009		Date and Hour of Discovery: July 11, 2009		
Was Immedi	nte Notice	Given? ⊠	Yes 🔲	No Not Requ	If YES, To V Ilred Mike Bratche	If YES, To Whom? Mike Bratcher, NMOCD; Jim Amos, BLM			
By Whom? F	radley Ble	vins		· · · · · · · · · · · · · · · · · · ·	Date and Ho	Date and Hours July 11, 2009 @ 2:20 PM			
Was a Water	course Rea	ched?	,			If YES, Volume Impacting the Watercourse:			
			Yes 🛛	No	Not Applicab	Not Applicable			
If a Watercourse was Impacted, Describe Fully.* Not Applicable									
Describe Cause of Problem and Remedial Action Taken. * Equipment failure at the location caused approximately 300 barrels of oil to be released.									
Approximately 242 barrels were recovered at the site. Soil was excavated to a depth of one (1) foot below ground surface, and transported to a State									
	approved disposal facility on July 13, 2009. Three (3) test trenches were excavated and sampled across the release area. On August 10, 2009, one (1) soil								
boring hole was advanced and samuled at depths of 5. 10. 15. and 19 feet bgs.									
Describe Area Affected and Cleanup Action Taken.* As per Remediation Proposal submitted to NMOCD by Environmental Plus, Inc., (EPI). On									
August 28, 2009, tank battery was relocated on existing pad, EPI excavated the spill site an additional +3ft bgs., removing approximately 2156 yds. of									
additional contaminated soil, and transporting to Lea Land landfarm. An additional Sample Trench was excavated to 24.5 ft bgs. and sampled for BTEX, TPH, and Chloride concentration on August 16, 2010. Laboratory results received from Cardinal Laboratories on August 17, 2010 indicated the BTEX									
and TPH samples tested below NMOCD remedial threshold goals, and Chloride concentration tested at 448 mg/kg. Water depth being at approximately									
356 bgs., chances of contamination are remote. However, a 40-mil plastic liner was installed to prevent possible groundwater contamination. Splil site									
was backfilled using overburden from recent tank battery construction. On September 24, 2010, 15 lbs. of BLM seed mix #2 and 10 lbs. of BLM seed mix									
#4 were drill seeded and site was cultivated to facilitate vegetation growth on previously contaminated area.									
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and									
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability									
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health									
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other									
federal, state, or local laws and/or regulations.									
1						OIL CONSERVATION DIVISION			
L		10.	_8/	, ,					
Signatures	- Will	adily	que	uns	-	H/ha			
Signature: Stadley Flourie Approved by District Supervisor:									

Approval Date:

Phone: (575) 441-0341

Conditions of Approval:

* Attach Additional Sheets If Necessary

E-mail Address: bblevins@chkenergy.com

Printed Name: Bradley Blevins

Title: EH&S

Date: 10/12/2010

Attached 🔲

Expiration Date: 1