District II Energy Miner   811 S. First St., Artesia, NM 88210 Oil Cor   District III 001 Cor   1000 Rio Brazos Road, Aztec, NM 87410 1220 Sc   District IV 1220 Sc   1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa						NM of New Mexico als and Natural Resources servation Division uth St. Francis Dr. Fe, NM 87505 ion and Corrective Ac OPERATOR Contact Lucas Smith Telephone No. 539-573-017			Initial Report 🔲 Final Report		
Facility Nat					Facility Type : Oil and Gas Well						
Surface Owner: Federal Mineral Owne						Federal API No. 30-015-42220					
LOCATION OF RELEASE											
Unit Letter						South Line Feet from the East/West Li			st Line	County	
A ·	A · 35 25S 29E		300	FNL		260	FEL		Eddy		
			·	Latitude: 32.0	92610	Longitude	:-103.9468205			<u> </u>	
Latitude: 32.0926101 Longitude: -103.9468205 NATURE OF RELEASE											
	Type of Release. Produced Water						Volume of Release: 30 Bbls Volume Recovered: 28 Bbls				
Source of Release Dump valve malfunction sent produced water to flare						Date and Hour of OccurrenceDate and Hour of Discovery04/15/1604/15/16 - 1500hrs MT					
Was Immedia		iven?			If YES, To Whom?						
🗌 Yes 🔲 No 🛛 Not Required						Message left at Artesia Field Office					
By Whom? Lucas Smith						Date and Hour: 04/16/16-1208hrs MT					
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.					
If a Watercourse was Impacted, Describe Fully.* N/A											
Describe Cause of Problem and Remedial Action Taken.* Dump valve malfunction sent produced water to flare											
Describe Are	a Affected ar	nd Cleanup A	Action Tal	cen,*							
Describe Area Affected and Cleanup Action Taken.* Fluid was standing around the flare. Vacuum truck was dispatched to recover free standing fluid, approximately 28 Bbls recovered. Offsite affected soil will be dug and hauled. Confirmation samples will be collected.											
regulations al public health should their o	Il operators a or the enviro operations ha nment. In ad	re required to onment. The ve failed to a dition, NMC	o report an acceptance idequately ICD accept	nd/or file certain r ce of a C-141 repo investigate and r	elease no ort by the emediate	otifications and NMOCD m e contaminati	nd perform correc arked as "Final R on that pose a thr	tive action eport" does cat to grou	s for rele s not reli nd water	suant to NMOCD rules and eases which may endanger ieve the operator of liability r, surface water, human health ompliance with any other	
Signature:						OIL CONSERVATION DIVISION					
Printed Name	e: Lucas Smi		· · · ·	Approved by	Environmental S	pecialist:	$M^2$	jun			
Title: EHS N	Aanager				Approval Dat	e: 4119111	e Exp	oirat <u>ion</u>	Date: NHA		
E-mail Addre	ess: Lucas.sr	nith@woxen	ergy.com			Conditions of	Approval:				
						Remediation per O.C.D. Rules & Guidelines					
Date: 04/18/16 Phone: 539-573-0176 SUBMIT REMEDIATION PROPOSAL NO											
· Auach Addi	uonai Sneet	IS IT INCCESS	ary		L	ATER TH	AN: <u>617</u>	$\omega_{16}$		2RP-3649	

## Patterson, Heather, EMNRD

From:	Smith, Lucas <lucas.smith@wpxenergy.com></lucas.smith@wpxenergy.com>
Sent:	Monday, April 18, 2016 9:44 AM
То:	Patterson, Heather, EMNRD
Subject:	WPX Energy/RKI North Brushy Draw 35-9H Spill
Attachments:	20160418104832706.pdf

Heather, thank you for your time this morning. I have a little learning curve for NM but plan to get up to speed quickly.

*Lucas Smith Environmental Health and Safety Manager* WPXENERGY.

.

539-573-0176 (Office) 817-727-9716 (Cell) lucas.smith@wpxenergy.com

*Quote:* "In any moment of decision, the best thing you can do is the right thing. The worst thing you can do is nothing." *Theodore Roosevelt 26th U.S. President*