

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

State of New Mexico
Energy Minerals and Natural Resources

APR 20 2016

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.**RECEIVED**Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505**Release Notification and Corrective Action**

NAB 1611226146

6137

OPERATOR

☒ Initial Report☒ Final Report

Name of Company Devon Energy Production Company	Contact William Carter, Assistant Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-513-0956
Facility Name Snapping 2 State #4H	Facility Type Oil

Surface Owner State	Mineral Owner State	API No 30-015-39071
----------------------------	----------------------------	----------------------------

LOCATION OF RELEASE

Unit Letter P	Section 2	Township 26S	Range 31E	Feet from the 330	North/South Line South	Feet from the 735	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude: N 32.0657806 Longitude: W -103.7426834

NATURE OF RELEASE

Type of Release Spill Oil & Produced Water	Volume of Release 7 BBLs	Volume Recovered 7 BBLs
Source of Release Vent tank	Date and Hour of Occurrence 4/17/2016 @ 1:25 am	Date and Hour of Discovery 4/17/2016 @ 1:25 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD-Mike Bratcher BLM Shelly Tucker	
By Whom? William Carter, Assistant Production Foreman	Date and Hour OCD- 4/17/16 @ 3:30 pm BLM- 4/17/16 @ 3:45 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*

The micro switch on the two phase separator dump failed causing the separator to swamp out resulting in a release from the vent tank. The pump was immediately shut down via the drive and then the tubing and casing valves were closed at the wellhead to prevent further release.

Describe Area Affected and Cleanup Action Taken.*

Approximately 1 BBL of oil and 6 BBLs produced water was released from the vent tank into lined containment. Approximately all 7 BBLs oil and produced water remained in the lined containment. None of the released fluid left pad. Liner was checked for holes and no holes were found. A vacuum truck was called and recovered approximately all 7 BBLs of oil and produced water from the lined containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sarah Gallegos-Troublefield	OIL CONSERVATION DIVISION	
Printed Name: Sarah Gallegos-Troublefield	Signed By <i>Mike Bratcher</i>	
Title: Field Admin Support	Approved by Environmental Specialist:	
E-mail Address: Sarah.Gallegos-Troublefield@dmv.com	Approval Date: 4/21/16	Expiration Date: N/A
Date: 4/20/2016 Phone: 575.748.1864	Conditions of Approval: FINAL	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-3653

Bratcher, Mike, EMNRD

From: Gallegos-Troublefield, Sarah <Sarah.Gallegos-Troublefield@dvn.com>
Sent: Wednesday, April 20, 2016 12:50 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; agroves@slo.state.nm.us
Cc: Scrogum, Sandy
Subject: Snapping 2 State #4H_7 BBLS Oil & PW_4-17-16
Attachments: Snapping 2 State #4H_7 BBLS Oil & PW-4-17-16.doc; Snapping 2 State #4H_7 BBLS Oil & PW-4-17-16-GIS Image.pdf; Snapping 2 State #4H_7 BBLS Oil & PW-4-17-16-Pic 1 of 1.jpg

Good afternoon,

Attached is the Initial & Final C-141, GIS Image and 1 photo of the 7 BBLS Oil & Produced water release that occurred at the Snapping 2 State #4H on 4/17/2016. Please be advised that the blue dot in the GIS Image represents the approximate location of the origin of the release.
Please contact me for any question you may have.

Thank you very much!

Respectfully,

Sarah Gallegos-Troublefield
Field Admin Support
Production

Devon Energy Corporation
P.O. Box 250
Artesia, NM 88211
575 748 1864 Direct Line



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.