

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1611933379 **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. 2140737	Contact: Amy Ruth	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329	
Facility Name: James Ranch Unit #12H	Facility Type: Exploration and Production	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-22162

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	21	22S	30E	1450	North	1830	East	Eddy

Latitude 32.380700° Longitude -103.884298°

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	24 bbls	Volume Recovered	10 bbls
Source of Release	Line Failure from Jet Pump to Well	Date and Hour of Occurrence	4/21/2016 time unknown	Date and Hour of Discovery	4/21/2016 2:20 pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	N/A		
By Whom?	N/A	Date and Hour	N/A		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

NM OIL CONSERVATION
ARTESIA DISTRICT

APR 27 2016

RECEIVED

If a Watercourse was Impacted, Describe Fully.*
N/A



Describe Cause of Problem and Remedial Action Taken.*

Collar on pressurized steel line corroded and fluids escaped to ground surface. Line was isolated and exposed. Line will be replaced.

Describe Area Affected and Cleanup Action Taken.*

The leak affected 900 square feet of well pad. Standing fluids were recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amy C. Ruth	Approved by Environmental Specialist: 	
Title: EHS Remediation Specialist	Approval Date: 4/28/16	Expiration Date: N/A
E-mail Address: ACRuth@basspet.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 4/27/2016 Phone: 432-661-0571	SUBMIT REMEDIATION PROPOSAL NO	

LATER THAN: 5/28/16

2RD-3662

* Attach Additional Sheets If Necessary

Patterson, Heather, EMNRD

From: Ruth, Amy C. <ACRuth@BassPet.Com>
Sent: Wednesday, April 27, 2016 10:49 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: jamos@blm.gov
Subject: JRU 12H 4-21-16 Leak
Attachments: Initial C-141 - JRU 12H 4-21-16.pdf; IMG_1148.JPG

Here is an initial form C-141 for a recent event on our Drill Island #1 on Cimarron Road. Also attached is a photo. The spill remained on the pad and our operations are in discussion about replacing the entire line from the pump to the well. FYI.



Amy C. Ruth
BOPCO, L.P.
EH&S Remediation Specialist
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office: (575)887-7329
Fax: (575)887-7473
Cell: (432)661-0571