NM OIL CONSERVATION

ARTESIA DISTRICT

District I 1625 N. French Dr., Hobbs. NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road. Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

MAY 04 2016

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 RECEIVE by to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action													
	<u> </u>	<u> 52794</u>	OPERATOR										
Name of Co		Oxy Permial		<u> Lolo91</u>	Contact Casey Summers Telephone No. (575) 513-8289								
Address 6 Desia Drive, Midland, TX 79705 Telephone No. (575) 513-8289 Facility Name Nimitz 12 Federal #3H Facility Type Well													
Surface Owner BLM Mineral Owner API No. 30-015-41011													
LOCATION OF RELEASE													
Unit Letter	Section	Township	Range	Feet from the		South Line Feet from the		East/West Line		County			
В	12	245	30E						Edr		Eddy County, NM		
Latitude <u>N 32.23885°</u> Longitude <u>W 103.83234°</u>													
NATURE OF RELEASE													
Type of Release Oil and Produced water							olume of Release 2 bbl oil, Volume Recovered 2 bbls bbls produced water					5	
Source of Release Stuffing box packing blew out							lour of Occurrenc	e	Date and	1 Hour of Discovery			
Was Immediate Notice Given?						04/22/2016 If YES, To Whom?							
By Whom? Kathy@ BBC International, Inc.						Date and Hour 04/22/2016 @ 3:56 pm If YES, Volume Impacting the Watercourse.							
Was a Watercourse Reached? ☐ Yes ☑ No							olume Impacting t	he Wate	rcourse.				
If a Watercou	rse was lm	pacted, Descri	ibe Fully,	I						-			
Describe Cause of Problem and Remedial Action Taken.*													
The packing blew out of the stuffing box causing a spill of 2 bbls of oil and 3 bbls of produced water. A vacuum truck recovered 2 bbls of fluids and the packing was replaced.													
Describe Area Affected and Cleanup Action Taken.*													
The affected area is approximately 250' x 25' on location near the well head with a small overspray area just west of location. Remediation will be completed in accordance with a remediation plan approved by both NMOCD and the BLM.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger													
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have/failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other													
federal, state, or local laws/and/or regulations. OIL CONSERVATION DIVISION													
1./-						SIE CONSERVATION DIVISION							
Signature: //~/							Approved by Environmental Specialist Like Branches						
Printed Name	: Casey	Summers		,		Approved by	Environmental S	pecialist	1777	NETATE	10.34	-	
Title: NM Environmental Advisor						Approval Date: 5 5 16 Expiration Date: N/A							
E-mail Address: Casey Summers@oxy.com							Conditions of Approval:						
F-(1-16						Conditions of Approval Remediation per O.C.D. Rules & Guidelingshed SUBMIT REMEDIATION PROPOSAL NO							
Date:		T I No	Phone	: (575) 513-82	89 5	UBMIT R ATER TH	EMEDIATION	77/8	TUJAL		<u> </u>		
Attach Addi	ORC IGNOU	CIS II NECUSS	ar y		L	AIEK IN	717.— <i>——————————————————————————————————</i>	100		21	ф .	3673	

Bratcher, Mike, EMNRD

From:

Kathy Purvis <kathy@bbcinternational.com>

Sent:

Wednesday, May 04, 2016 2:30 PM

To:

Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov

Cc:

Casey_Summers@oxy.com; dusty_wilson@oxy.com; Jennifer_duarte@oxy.com;

cbrunson@bbcinternational.com; kswinney@bbcinternational.com;

jgilkey@bbcinternational.com

Subject:

Initial C-141, Nimitz 12 Federal #3H

Attachments:

Initial C-141, Nimitz 12 Federal #3H.pdf

Attached is the initial C-141 for a leak that occurred at the Nimitz 12 Federal #3H on 04/22/2016 in Eddy County, NM. Receipt notification via email is greatly appreciated.

Kathy Purvis BBC International, Inc. 1324 W. Marland Hobbs, NM 88240 Phone: (575) 397-6388

Fax: (575) 397-0397

Email: kathy@bbcinternational.com

Patterson, Heather, EMNRD

From:

Kathy Purvis <kathy@bbcinternational.com>

Sent:

Friday, April 22, 2016 3:56 PM

To:

Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov

Cc:

 $Casey_Summers@oxy.com; \ dusty_wilson@oxy.com; \ Jennifer_duarte@oxy.com;$

cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com; kathy@bbcinternational.com

Nimitz 12 Federal #3H

Subject:

This is to inform you that Oxy Permian had a leak at the Nimitz 12 Federal #3H on April 22, 2016. Oxy spilled 2 bbls of oil and 3 bbls of produced water due the stuffing box packing blowing out. The preliminary report shows the leak measuring approximately 10' x 60' on location near the well head. Recovery is in progress. The release is located in U/L B of Section 12, T24S, R30E of Eddy County, NM. BBC International will remediate the location at a later date and an initial C-141 will follow. Driving directions: From Carlsbad on US285, turn left on NM31 and go 7 miles, turn right on NM128 and go east to Twin Wells Rd, turn south and go 6 miles, turn right and go west on dirt road 1 mile, turn left and go 100 yards to location. API# 30-015-41011 GPS coordinates: N 32.23877° N 103.83220°

Kathy Purvis BBC International, Inc. 1324 W. Marland Hobbs, NM 88240 Phone: (575) 397-6388

Fax: (575) 397-0397

Email: kathy@bbcinternational.com