


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003

Submit to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company <b>Devon Energy</b>	Contact <b>Roy White, Foreman</b>	
Address <b>6488 Seven Rivers Hwy - P.O. Box 250</b>	Telephone No. <b>575-513-1741</b>	
Facility Name <b>Laguna Salado 22 Fed 4H</b>	Facility Type <b>Oil Well</b>	
Surface Owner	Mineral Owner	Lease No.

**LOCATION OF RELEASE**

Unit Letter <b>C</b>	Section <b>22</b>	Township <b>23S</b>	Range <b>29E</b>	Feet from the <b>1172</b>	North/South Line <b>FNL</b>	Feet from the <b>2510</b>	East/West Line <b>FWL</b>	County <b>Eddy</b>
-------------------------	----------------------	------------------------	---------------------	------------------------------	--------------------------------	------------------------------	------------------------------	-----------------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release <b>Produced Water</b>	Volume of Release <b>10 bbls</b>	Volume Recovered <b>0 bbls</b>
Source of Release <b>Overflowed Frac Tanks</b>	Date and Hour of Occurrence <b>03-31-2011 - 8:00 am</b>	Date and Hour of Discovery <b>03-31-2011 - 10:25am</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Eugene Abernathy with, Mosaic</b>	
By Whom? <b>Jerry Mathews with Devon Energy</b>	Date and Hour <b>03-31-2011 - 10:25 am</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* **The flow back hand fell asleep and he was terminated**

Describe Area Affected and Cleanup Action Taken.\*  
**The area affected was a caliche road. MOSAIC requested we scratch the road surface and lay new caliche, which we did.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <b>Mykol Horner</b>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Mykol Horner</b>	Approved by District Supervisor:	<b>Accepted for record NMOCD</b> <i>-Styke</i>
Title: <b>Field Tech 1</b>	Approval Date: _____	Expiration Date: _____
E-mail Address: <b>mykol.horner@dvn.com</b>	Conditions of Approval: _____	Attached <input type="checkbox"/>
Date: _____ Phone: <b>575-748-0160</b>		

\* Attach Additional Sheets If Necessary

*ZRP-716*