

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

MAR 16 2010

NMOCD ARTESIA

Form C-141
Revised October 10, 2003
Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Plains Pipeline, LP	Contact	Jason Henry
Address	2530 Hwy 214 - Denver City, Tx 79323	Telephone No.	(575) 441-1099
Facility Name	Loco Hills Station Bypass Line	Facility Type	Pipeline
Surface Owner	BLM	Mineral Owner	
		Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	23	17S	31E					Eddy

Latitude N 32° 49' 23.4" Longitude W 103° 50' 15.6"

NATURE OF RELEASE

Type of Release	Crude Oil	Volume of Release	35 bbls	Volume Recovered	25 bbls
Source of Release	4" Steel Bypass Line	Date and Hour of Occurrence	11/19/2009	Date and Hour of Discovery	11/19/2009 11:00
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Verbal notification to Mike Bratcher on 11/20/2009			
By Whom?	Jason Henry	Date and Hour 11/20/2009 @ 10:30			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					



Describe Cause of Problem and Remedial Action Taken.*

Internal corrosion of a 4-inch bypass line resulted in a release of crude oil, the free product was recovered with a vacuum truck, and the impacted soil was excavated, stockpiled, and remediated on-site. The excavated area was backfilled with the remediated stockpile.

Describe Area Affected and Cleanup Action Taken.*

The released crude resulted in a surface stain that measured approximately 40' x 30'. The impacted area was remediated per applicable BLM/NMOCD guidelines. Please see the attached Basin Environmental Consulting Remediation Summary and Site Closure Request for details of remedial activities conducted at the site.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jason Henry	Approved by District Supervisor: 	
Title: Remediation Coordinator	Approval Date: 5/20/10	Expiration Date: N/A
E-mail Address: jhenry@paalp.com	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: 02/26/2010	Phone: (575) 441-1099	

* Attach Additional Sheets If Necessary