

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

JUN 07 2016

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1616055657

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Devon Energy Production	Contact Jake Harrington, Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 432-214-5175
Facility Name Snapping 2 State I-Y	Facility Type Oil

Surface Owner State	Mineral Owner State	API No. 30-015-39104
---------------------	---------------------	----------------------

LOCATION OF RELEASE

Unit Letter N	Section 2	Township 26S	Range 31E	Feet from the 330	North/South Line FSL	Feet from the 1710	East/West Line FWL	County Eddy
------------------	--------------	-----------------	--------------	----------------------	-------------------------	-----------------------	-----------------------	----------------

Latitude: 32.0657578

Longitude: -103.7519608

NATURE OF RELEASE

Type of Release Natural Gas	Volume of Release 60 MCF	Volume Recovered 0 MCF
Source of Release Buy back gas line	Date and Hour of Occurrence June 3, 2016 @ 11:30 AM	Date and Hour of Discovery June 3, 2016 @ 11:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Shelly Tucker, BLM Mike Bratcher, OCD	
By Whom? Ray Carter, Asst. Production Foreman	Date and Hour Shelly Tucker, BLM June 6, 2016 @ 7:50 AM Mike Bratcher, OCD June 6, 2016 @ 7:55 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

Two check valves on the buyback line failed causing the line to rupture releasing 60 MCF. The valves on both sides of the line were immediately shut to stop any further release.

Describe Area Affected and Cleanup Action Taken.*

The line ruptured causing a 60 MCF air release. The valves have been replaced to correct the failure. No further action is required.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sheila Fisher	OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher	Signed By <u>Mike Bratcher</u>	
Title: Field Admin Support	Approved by Environmental Specialist:	Approval Date: 6/8/16 Expiration Date: N/A
E-mail Address: Sheila.Fisher@dvn.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 6/6/16 Phone: 575.748.1829		

* Attach Additional Sheets If Necessary

ARP-3723

Bratcher, Mike, EMNRD

From: Fisher, Sheila <Sheila.Fisher@devon.com>
Sent: Tuesday, June 07, 2016 3:34 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Carter, Ray; Harrington, Jake; Fulks, Brett
Subject: Snapping 2 State 1-Y_60 MCF air release_6.3.16
Attachments: Snapping 2 State 1-Y_60 MCF air release_Initial & Final C-141_6.3.16.doc; Snapping 2 State 1-Y_60 MCF air release_GIS Image_6.3.16.pdf; Snapping 2 State 1-Y_60 MCF air release_pic 1 of 1_6.3.16.jpg

Good Afternoon,

Attached please find the Initial & Final C-141, GIS Image and photo for the 60 MCF air release at the Snapping 2 State 1-Y.

If you have any questions please feel free to contact me.

Thank you

Sheila Fisher
Field Admin Support
Production
B-Schedule

Devon Energy Corporation
PO Box 250
Artesia, NM 88211
575 748 1829 Direct



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.