

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

JUN 23 2016

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB 1617427149
Name of Company *Cimarex Energy* *102483* OPERATOR ☒ Initial Report ☐ Final Report
Address 600 N Marienfeld Ste 600 Midland TX Contact Christine Alderman
Facility Name Crow Flats 16 State #2 Telephone No. 432-853-7059
Facility Type Production
Surface Owner Mineral Owner API No. 30-015-35556

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	16	16S	28E	660	S	330	W	Eddy

Latitude 32.91713 Longitude -104.18829

NATURE OF RELEASE

Type of Release crude oil	Volume of Release 165 bbls	Volume Recovered 85 bbls
Source of Release steel tank	Date and Hour of Occurrence 6/20/2016	Date and Hour of Discovery 6/20/2016
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/Heather Patterson	
By Whom? Christine Alderman	Date and Hour 6/21/2016 1:08pm #via e-mail	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.

Describe Cause of Problem and Remedial Action Taken.

The crude oil stock tank developed a hole in the bottom of it.

Describe Area Affected and Cleanup Action Taken.

The tank battery is lined with plastic liner and thick gravel. While recovering fluids a tear was noticed in the liner.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Christine Alderman</i>	OIL CONSERVATION DIVISION	
Printed Name: Christine Alderman	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: ESH Supervisor	Approval Date: 6/23/16	Expiration Date: N/A
E-mail Address: calderman@cimarex.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO	
Date: 6/23/2016 Phone: 432-853-7059	LATER THAN: 7/27/16 <i>2RP-3755</i>	

* Attach Additional Sheets If Necessary

Patterson, Heather, EMNRD

From: Christine Alderman <calderman@cimarex.com>
Sent: Thursday, June 23, 2016 10:57 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Subject: FW: Crow Flats 16 State #2 (API 30-015-35556)
Attachments: 20160623105215806.pdf

Please see attached C-141.

Thank you,

Christine Alderman

Cimarex Energy Co.



ESH Supervisor – Permian Basin
Midland TX
Cell – 432.853.7059

From: Christine Alderman
Sent: Tuesday, June 21, 2016 2:08 PM
To: mike.bratcher@state.nm.us; Patterson, Heather, EMNRD (Heather.Patterson@state.nm.us)
<Heather.Patterson@state.nm.us>
Cc: Gloria Garza <ggarza@cimarex.com>
Subject: Crow Flats 16 State #2 (API 30-015-35556)

Mike/Heather,

On June 20th we had a hole develop in one of our steel oil tanks at the above named location. Approximately 165 bbls were released into a plastic lined, gravel and dirt filled berm. We are still in the process of recovering fluids and I will send a C-141 and final recovery volume as soon as I have it.

Thank you!

Christine Alderman

Cimarex Energy Co.



ESH Supervisor – Permian Basin
Midland TX
Cell – 432.853.7059

Patterson, Heather, EMNRD

From: Christine Alderman <calderman@cimarex.com>
Sent: Tuesday, June 21, 2016 1:08 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Gloria Garza
Subject: Crow Flats 16 State #2 (API 30-015-35556)

Mike/Heather,

On June 20th we had a hole develop in one of our steel oil tanks at the above named location. Approximately 165 bbls were released into a plastic lined, gravel and dirt filled berm. We are still in the process of recovering fluids and I will send a C-141 and final recovery volume as soon as I have it.

Thank you!

Christine Alderman

Cimarex Energy Co.



ESH Supervisor – Permian Basin
Midland TX
Cell – 432.853.7059