

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT Form C-141
Revised August 8, 2011

JUL 15 2016

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1620 027656

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Yates Petroleum Corporation	25575	Contact Chase Settle
Address 104 S. 4 th Street, Artesia, NM 88210		Telephone No. 575-748-4171
Facility Name Dagger ZW Battery		Facility Type Battery

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-25787
--------------------------	--------------------------	-------------------------

LOCATION OF RELEASE

Unit Letter K	Section 30	Township 19S	Range 25E	Feet from the 1980	North/South Line South	Feet from the 1980	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.62982 Longitude -104.52613

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 11 B/O	Volume Recovered 8 B/O
Source of Release Crude Oil Tank	Date and Hour of Occurrence 7/1/2016; 12:30 p.m.	Date and Hour of Discovery 7/1/2016; 12:30 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	



If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

The crude oil tank developed a hole which led to the release of crude oil.

Describe Area Affected and Cleanup Action Taken.* An approximate area of 90' X 17' was affected within the berm of the battery. Vacuum trucks were called to remove standing fluid, and impacted soils will be excavated and hauled to a NMOC approved facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's (site ranking is 0) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL's a work plan will be submitted to the OCD. Depth to Ground Water: >100' (approximately 235', Section 30, T19S-R25E, per Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Chase Settle	Approved by Environmental Specialist: 	
Title: NM Environmental Representative	Approval Date: 7/15/16	Expiration Date: N/A
E-mail Address: csettle@yatespetroleum.com	Conditions of Approval:	
Date: 07/15/2016	Phone: 575-748-4171	

Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 7/15/16

2RP-3782

Patterson, Heather, EMNRD

From: Chase Settle <CSettle@yatespetroleum.com>
Sent: Friday, July 15, 2016 12:37 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Jim Amos
Cc: Bob Asher; Veronica Alvarado
Subject: C-141 Initial Dagger ZW Battery
Attachments: C-141 Dagger ZW Battery_2016_07_01_Initial.pdf

Please find attached the C-141 Initial for the below listed location.

Dagger ZW Battery
30-015-25787
Section 30, T19S-R25E
1980 FSL & 1980 FWL
Eddy County, New Mexico

Thank you,

Chase Settle, M.S.
Environmental Representative
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4171 (Office)
575-703-6537 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
