




AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pJXK1621139065

1RP - 4375

NEW MEXICO SALT WATER DISPOSAL CO., INC

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

RECEIVED

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OCT 05 2010

HOBBSOCD

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	New Mexico Salt Water Disp. Co.	Contact	James B. Read
Address	P. O. Box 1518, Roswell, NM 88202	Telephone No.	575-622-3770 ext. 310
Facility Name	Pipeline	Facility Type	Pipeline

Surface Owner	State of New Mexico	Mineral Owner		Lease No.	
---------------	---------------------	---------------	--	-----------	--

LOCATION OF RELEASE

30 025 0424

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	15	10S	34E	330	South	330	West	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	500 bbls	Volume Recovered	working
Source of Release	Tank	Date and Hour of Occurrence		Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jeff Leking	Occurred:	Weekend
By Whom?	James B. Read	Date and Hour	10/04/2010	Discovered:	10/03/2010 P.M.
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Leak in Pipeline probably due to weather in area. Rain, lightening and increment weather in area.

Describe Area Affected and Cleanup Action Taken.*

Water immediately recovered. Excavate impacted soil, and backfill with clean soil if necessary.
Submit mediation plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>James B. Read</i>	By: <i>Holly Barajas</i>		OIL CONSERVATION DIVISION	
Printed Name: James B. Read	Approved by: <i>Jeffrey Leking</i>		ENV. ENGINEER'S District Supervisor: _____	
Title: Agent	Approval Date: 10/13/10	Expiration Date: 12/13/10		
E-mail Address: jbro@brightok.net	Date: 10/04/2010		Phone: 575-622-3770	
Conditions of Approval: DELIVER TO CLEANUP +1. SUBMIT FINAL C-141 BY 12/13/10		Attached <input type="checkbox"/> WRP-10-10-2633		

* Attach Additional Sheets If Necessary

4375