

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

AUG 19 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

PAB1623629683
NAB162363164

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Yates Petroleum Corporation	25575	Contact Amber Griffin
Address 105 S. 4 th Street Artesia, NM 88210		Telephone No. 575-748-1471
Facility Name Dayton Townsite Water System (Williams Water Line)		Facility Type PVC Flow Line

Surface Owner Donald Fanning and Sons	Mineral Owner	API No.
--	---------------	---------

LOCATION OF RELEASE

Unit Letter	Section 25	Township 18S	Range 26E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32.72062 Longitude 104.34295

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release Unknown B/PW	Volume Recovered 1 B/PW
Source of Release PVC Flow Line	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 8/9/2016; PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour: N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*

There was a leak on a 4" PVC flow line. Wells in the area were shut in and the line was isolated. A crew was called to put a fence around the release area. The line has been taken out of service.

Describe Area Affected and Cleanup Action Taken.

The affected area is approximately 0.3554 acres in the pasture. The area was scraped to remove visibly impacted soils and the soils were taken to a NMOC approved disposal facility. Vertical and horizontal delineation samples have been taken from the release area and analysis will be run for TPH, BTEX, and Chlorides. If initial analytical results are under RRAL's (site ranking is 20) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL's a work plan will be submitted to the OCD. Depth to Ground Water: <50' (approximately 35', per 24-18S-26E, NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 20.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <u>Amber Griffin</u>	SIGNED BY <u>[Signature]</u>	
Printed Name: Amber Griffin	Approved by Environmental Specialist	
Title: Environmental Representative	Approval Date: <u>8/23/16</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>agriffin@yatespetroleum.com</u>	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO	
Date: August 19, 2016	Phone: 575-748-4111	LATER THAN: <u>9/23/16</u>

* Attach Additional Sheets If Necessary

2RP. 3840

Bratcher, Mike, EMNRD

From: Amber Griffin <AGriffin@yatespetroleum.com>
Sent: Friday, August 19, 2016 1:48 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Veronica Alvarado
Subject: Dayton Townsite Water System (Williams Water Line)
Attachments: DaytonTownsiteWaterSystem(WilliamsWaterLine)_C141_080916 Initial.pdf

Please find attached an Initial C-141 for a release that was discovered at the Dayton Townsite Water System (Williams Water Line) on August 9, 2016. When a RP# is assigned to this site, can you please let me know?

Please let me know if there are any questions.

Thank you,

Amber Griffin

Environmental Representative
Yates Petroleum Corporation
Office: (575) 748-4111
Cell: (575) 513-8799

20160819 1:48 PM
AGriffin@yatespetroleum.com
Bratcher, Mike, EMNRD
Patterson, Heather, EMNRD
Veronica Alvarado