

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

AUG 26 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Form C-141
Revised August 8, 2011

FAB1623951305 Release Notification and Corrective Action

NAB1623951503

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Yates Petroleum Corporation	Contact Chase Settle
Address 104 S. 4 th Street, Artesia, NM 88210	Telephone No. 575-748-4171
Facility Name Livingston Ridge SWD System	Facility Type Pipeline

Surface Owner Federal	Mineral Owner Federal	API No.
--------------------------	--------------------------	---------

LOCATION OF RELEASE

Unit Letter H	Section 35	Township 22S	Range 31E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32.35518 Longitude -103.74062

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 30	Volume Recovered 5
Source of Release 6 inch poly produced water line	Date and Hour of Occurrence 8/10/2016; 12:00 p.m.	Date and Hour of Discovery 8/10/2016; 12:00 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson, Shelly Tucker	
By Whom? Bob Asher	Date and Hour 8/11/2016; 8:19 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		



Describe Cause of Problem and Remedial Action Taken.*

Vacuum truck was called to the release site to retrieve standing fluid, and a roustabout crew was dispatched to repair the poly line.

Describe Area Affected and Cleanup Action Taken.* An approximate area of 40' X 50' was affected around the 6" poly produced water line. Impacted soils will be excavated and hauled to a NMOC approved facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's (site ranking is 0) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL's a work plan will be submitted to the OCD. **Depth to Ground Water: >100' (approximately 120', Section 35, T22S-R31E, per Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Chase Settle	Approval Date: 8/26/16	Expiration Date: N/A
Title: NM Environmental Regulatory Agent	Conditions of Approval:	
E-mail Address: csettle@yatespetroleum.com	Attached <input type="checkbox"/>	
Date: 08/25/2016	Phone: 575-748-4171	

Remediation per O.C.D. Rules & Guidelines
SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 9/29/16

2RP-3846

Patterson, Heather, EMNRD

From: Chase Settle <CSettle@yatespetroleum.com>
Sent: Thursday, August 25, 2016 12:31 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Jim Amos; Tucker, Shelly
Cc: Bob Asher; Amber Griffin; Katie Parker; Veronica Alvarado
Subject: C-141 and Sundry Livingston Ridge SWD System
Attachments: C-141 Livingston Ridge SWD System_Initial_2016_08_10.pdf; Sundry Livingston Ridge SWD System_Initial_2016_08_10.pdf

Please find attached the C-141 Initial and Sundry for the below listed location.

Livingston Ridge SWD System
Section 35, T22S-R31E
Eddy County, New Mexico

Thank you,

Chase Settle, M.S.
Environmental Representative
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4171 (Office)
575-703-6537 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.

Patterson, Heather, EMNRD

From: Bob Asher <BobA@yatespetroleum.com>
Sent: Thursday, August 11, 2016 8:19 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov
Cc: Amber Griffin; Chase Settle; Katie Parker; Veronica Alvarado
Subject: Release Notification (Livingston Ridge Water System)

Yates Petroleum Corporation is reporting a release at the following location (8/10/2016, 1:02 PM).

Livingston Ridge Water Transfer System
Section 35, T22S-R31E
Eddy County, New Mexico

Released: 30 B/PW; Recovered: 5 B/PW.

Cause of the release was from a 6" poly water transfer line that ruptured. Vacuum truck(s) and roustabout crews were called. The release point is adjacent (east side) of CR 798/Red Road and approximately 0.25 miles north of the David Ross SWD #1. A Form C-141 with complete information will be submitted.

Thank you.

Robert Asher
Sr. Environmental Supervisor
Health & Environmental Department
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)
Yates Safety Begins With YOUR Safety

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
