

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

SEP 07 2016

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1625342050

OPERATOR

☒ Initial Report ☐ Final Report

| | | | |
|-----------------|----------------------------------|---------------|----------------|
| Name of Company | Oxy Permian Ltd. | Contact | Casey Summers |
| Address | 6 Desta Drive, Midland, TX 79705 | Telephone No. | (575) 513-8289 |
| Facility Name | Harroun 15 #3 & #5 CTB | Facility Type | Battery |

| | | | | | |
|---------------|-----|---------------|--|---------|--------------|
| Surface Owner | BLM | Mineral Owner | | API No. | 30-015-29233 |
|---------------|-----|---------------|--|---------|--------------|

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|-----------------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| H | 15 | 24S | 29E | | | | | Eddy County, NM |

Latitude N 32.22011° Longitude W 103.96463°

NATURE OF RELEASE

| | | | | | |
|-----------------------------|---|---|---|----------------------------|--------|
| Type of Release | Oil and Produced water | Volume of Release | 3 bbls oil, 7 bbls produced water | Volume Recovered | 9 bbls |
| Source of Release | Compromised 2" steel line from the separator | Date and Hour of Occurrence | 08/22/2016 | Date and Hour of Discovery | |
| Was Immediate Notice Given? | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? | Mike Bratcher, Heather Patterson- NMOCD; Shelly Tucker- BLM | | |
| By Whom? | Kathy Purvis @ BBC International Inc. | Date and Hour | 08/23/2016 @ 4:54 pm | | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | | | |

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A compromised 2" steel line from the separator leaked 3 bbls of oil and 7 bbls of produced water. A vacuum truck recovered 9 bbls of fluids and the line was repaired.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 10' x 20' both on and off location. Remediation will be completed in accordance with an approved remediation plan from NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | | | | |
|-----------------|--------------------------|---------------------------------------|--|--------------------------------|-----|
| Signature: | <u>[Signature]</u> | | OIL CONSERVATION DIVISION | | |
| Printed Name: | Casey Summers | Approved by Environmental Specialist: | <u>[Signature]</u> | | |
| Title: | NM Environmental Advisor | Approval Date: | 9/8/16 | Expiration Date: | N/A |
| E-mail Address: | Casey_Summers@oxy.com | Conditions of Approval: | Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Attached <input type="checkbox"/> | | |
| Date: | 9-7-16 | Phone: | (575) 513-8289 | SUBMIT REMEDIATION PROPOSAL NO | |

* Attach Additional Sheets If Necessary

THAN: 10/9/16

2RP-3878

Patterson, Heather, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Wednesday, September 07, 2016 4:32 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov
Cc: Casey_Summers@oxy.com; jennifer_duarte@oxy.com; 'Cliff Brunson'; 'Ken Swinney'; 'Jennifer Gilkey'
Subject: Harroun 15 #3 & #5 CTB
Attachments: Initial C-141, Harroun 15 #3 & #5 CTB.pdf

Attached is the initial C-141 for a leak that occurred at the Harroun 15 #3 & #5 CTB on 08/22/2016 in Eddy County, NM. Receipt notification and the RP number via email is greatly appreciated.

Kathy Purvis

BBC International, Inc.
1324 W. Marland Blvd.
Hobbs, NM 88240
Business: (575) 397-6388
Cell: (575) 441-8619
kathy@bbcinternational.com

Bratcher, Mike, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Tuesday, August 23, 2016 4:54 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov
Cc: Casey_Summers@oxy.com; jennifer_duarte@oxy.com; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; 'Jennifer Gilkey'; kathy@bbcinternational.com
Subject: Harroun 15 #3 & #5 CTB

This is to inform you that Oxy Permian had a release at the Harroun 15 #3 & #5 CTB on 08/22/2016. Oxy released 3 bbls of oil and 7 bbls of produced water due to a compromised 2" steel line from the separator. The preliminary report shows the leak measuring 10' x 20' both on and off location. Recovery is in progress. The release is located in U/L H of Section 15, T24S, R29E of Eddy County, NM. Driving directions: From Malaga, take CR720 to Harroun Rd, turn East and go across river to Lane Bridge sign, turn right at sign and road becomes dirt, go to compressor station sign and turn left, turn right just past compressor and go 1 mile, pass 1st CG and turn left to facility. GPS coordinates: N 32.22011° W 103.96463° API# 30-015-29233

Kathy Purvis

BBC International, Inc.
1324 W. Marland Blvd.
Hobbs, NM 88240
Business: (575) 397-6388
Cell: (575) 441-8619
kathy@bbcinternational.com