

NM OIL CONSERVATION

ARTESIA DISTRICT

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 S. First St., Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

 State of New Mexico
 Energy Minerals and Natural Resources

SEP 28 2016

 Form C-14
 Revised August 8, 20

 Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

 Submit 1 Copy to appropriate District Office
 accordance with 19.15.29 NMA
RECEIVED
Release Notification and Corrective Action

 #AB1627456818
 NAB1627457037

OPERATOR
☒ Initial Report ☐ Final Report

Name of Company DCP Midstream, LP	Contact Haskell Conder
Address 10 Desta Drive, Suite 400 West	Telephone No. cell 432-557-1127
Facility Name 10100 Ext 2 Gas Gathering Pipeline	Facility Type Natural Gas Gathering Pipeline

Surface Owner BLM	Mineral Owner	API No.
-------------------	---------------	---------

LOCATION OF RELEASE

Unit Letter	Section 5	Township 21S	Range 31E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------	-----------	--------------	-----------	---------------	------------------	---------------	----------------	-------------

Latitude 32.5056911 Longitude -103.7953421

NATURE OF RELEASE

Type of Release: Raw Natural Gas, Condensate	Volume of Release 7 bbl	Volume Recovered 0 bbl
Source of Release 10100 Ext 2 Gas Pipeline	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 9-26-2016
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* N / A

Describe Cause of Problem and Remedial Action Taken.*

DCPM was notified by Intrepid Potash Mine Co that there was a line leak in their area. DCPM dispatched field operators to shut in the line and blow down the line.

Describe Area Affected and Cleanup Action Taken.*

A cleanup plan will be submitted for BLM and OCD Approval. The excavation from the repairs will be left open until remediation can be completed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>HP Conder</i>		OIL CONSERVATION DIVISION	
Printed Name: Haskell Conder		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Compliance Coordinator		Approval Date: 9/28/16	Expiration Date: N/A
E-mail Address: hconder@dcpmidstream.com		Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 9-26-2016	Phone: 432-557-1127	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 11/9/16

2RP-3914

Patterson, Heather, EMNRD

From: Conder, Haskell P <HPConder@dcpmidstream.com>
Sent: Tuesday, September 27, 2016 3:47 PM
To: Patterson, Heather, EMNRD; Fbanos@blm.gov; Rpair@Blm.gov; Bratcher, Mike, EMNRD
Cc: Blair, Yvonne B
Subject: Line Leak C-141
Attachments: 10100 ext 2 C141 09 26 16.doc; IMG_1390.jpg

Attached is the C-141 and site photo for 10100 Ext 2 leak located east of Intrepid Potash mine. We will be replacing 3 joints of pipe approximately 120 feet . When the repairs are completed the site will be delineated and a cleanup plan will be submitted for your approval.

Thanks

Hack Conder
Compliance Coordinator
DCP Midstream, LP
1625 W. Marland
Hobbs, NM 88240
(432) 557- 1127 mobile
(575) 397-5584 office
(575) 397-5598 fax