

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural ResourcesOil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505Form C-141  
Revised October 10, 2003Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

## Release Notification and Corrective Action

NMLB0625048579

## OPERATOR

☒ Initial Report ☐ Final Report



Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 <sup>TH</sup> Street	API Number 30-013-25914	Telephone No. 505-748-1471
Facility Name Foster AN Battery	Facility Type Battery	
Surface Owner Fee	Mineral Owner Federal	Lease No.

## LOCATION OF RELEASE

Unit Letter A	Section 1	Township 20S	Range 24E	Feet from the 660	North/South Line North	Feet from the 660	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.60817 Longitude 104.53428

## NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 260 B/PW	Volume Recovered 250 B/PW
Source of Release Water Pump	Date and Hour of Occurrence 6/11/2006 - PM	Date and Hour of Discovery 6/11/2006 - PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, OCD, District II (Telephone & E-mail)	
By Whom? Bob Asher, Yates Petroleum Corporation	Date and Hour 6/12/2006, 3:49 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Water pump failed. Called vacuum truck.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 30' X 10'. Vacuum truck picked up standing fluids. Area to be evaluated. Depth to Ground Water: >100', Wellhead Protection Area: No. Distance to Surface Water Body: >1000', SITE RANKING IS 0.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION TIM GUM by MB	
Printed Name: Robert Asher	Approved by District Supervisor: 	
Title: Environmental Regulatory Agent	Approval Date: <u>6/17/06</u>	Expiration Date:
E-mail Address: boba@ypcnm.com	Conditions of Approval:	Attached <input checked="" type="checkbox"/>
Date: Thursday, July 13, 2006	Phone: 505-748-1471	

\* Attach Additional Sheets If Necessary