NM OIL CONSERVATION ARTESIA DISTRICT

<u>District I</u> 1625 N. French Dr., Hobbs. NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

OCT 19 2016

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Cony to appropriate District Office in RECEIVE produce with 19.15.29 NMAC.

Release Notification and Corrective Action													
NARI	10298	55846	. [OPERA T	OR	5	Initia	al Report	П	Final Report	
Name of Co				Ttolo9(o			asey Summers					7 11121 110 1101	
Address F	O Box 42	94, Houston	, TX 772		_ 7	Telephone N		-8289	,				
Facility Name Goodnight 27 Federal #002H							e Well						
Surface Owner BLM Mineral Owner API No. 30-015-43809													
	LOCATION OF RELEASE # 30-015-34/37												
							outh Line Feet from the East/West Line County				04/01		
L	27	238	29E						Eddy County, NM				
<u> </u>	Latitude N 32.27536° Longitude W 103.97690°												
Type of Release Oil and Produced water Volume of Release 5 bbls oil, Volume Recovered 10 bbls													
Type of Release Oil and Produced water							5 bbls produced water					15	
Source of Release Faulty valve on the well head							Date and Hour of Occurrence Date and Hour of Disc					Y	
Was Immediate Notice Given?						If YES, To	Whom?						
							Mike Bratcher, Heather Patterson- NMOCD; Shelly Tucker- BLM						
By Whom? Kathy@ BBC International, Inc.							Date and Hour 10/13/2016 @ 11:25 am If YES, Volume Impacting the Watercourse.						
Was a Watercourse Reached? ☐ Yes ☑ No							olume Impacting i	the Water	rcourse.				
If a Watercou	ırse was Im	pacted. Descr	ibe Fully.	*	L								
Describe Cause of Problem and Remedial Action Taken.*													
A faulty valve on the well head caused 5 bbls of oil and 5 bbls of produced water to leak onto the ground. A vacuum truck recovered 10 bbls of fluids and													
the valve was replaced.													
Describe Area Affected and Cleanup Action Taken.*													
The effected	is		د. د ۱۸۸۰ -	a location Doma	dintina .	will be seemed						h., b.ash	
The affected area is approximately 125'x 100' on location. Remediation will be completed in accordance with a remediation plan approved by both NMOCD and the BLM.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or logal laws and/or regulations.													
							OIL CON	SERV	ATION	DIVISI	<u>ON</u>		
Signature:									P.1 .	,			
							Environmental B	Sandial !	14 8	PARTELLE	F0		
Printed Name	e: Casey	Summers				——————————————————————————————————————		precimis	<u> </u>				
Title: NM Environmental Advisor							te: 10 24 1		Expiration	Date: N	A		
E-mail Address: <u>Casey_Summers@oxy.com</u>							f Annroyal:	J					
LO 10 10							Conditions of Approval: Remediation per O.C.D. Rules & Guidelines						
Date:	11-10	1-10	Phone	: (575) 513-83	289	SUBMIT REMEDIATION PROPOSAL NO							
* Attach Addi	tional She	ets If Neces	sary			LATER T	HAN:\\\	Ale			arf	>-3948	

Bratcher, Mike, EMNRD

From:

Kathy Purvis <kathy@bbcinternational.com>

Sent:

Wednesday, October 19, 2016 3:25 PM

To:

Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; 'Tucker, Shelly'

Cc:

Casey_Summers@oxy.com; Jennifer_Hudgens@oxy.com;

cbrunson@bbcinternational.com; kswinney@bbcinternational.com;

jgilkey@bbcinternational.com

Subject:

Initial C-141, Goodnight 27 Federal #002H

Attachments:

Initial C-141, Goodnight 27 Federal #002H.pdf

Attached is the initial C-141 for a leak that occurred at the Goodnight 27 Federal #002H on 10/12/2016 in Eddy County, NM. Receipt notification and the RP number are greatly appreciated.

Kathy Purvis

BBC International, Inc. 1324 W. Marland Blvd. Hobbs, NM 88240

Business: (575) 397-6388 Cell: (575) 441-8619

kathy@bbcinternational.com

Bratcher, Mike, EMNRD

From:

Kathy Purvis <kathy@bbcinternational.com>

Sent:

Thursday, October 13, 2016 11:25 AM

To:

Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; 'Tucker, Shelly'

Cc:

Casey_Summers@oxy.com; Jennifer_Hudgens@oxy.com;

cbrunson@bbcinternational.com; kswinney@bbcinternational.com;

igilkey@bbcinternational.com; kathy@bbcinternational.com

Subject:

Goodnight 27 Federal #002P

This is to inform you that Oxy Permian had arrelease at the Goodnight 27 Federal #002H on October 12, 2016. Oxy released 5 bbls of oil and 5 bbls of produced water due to a faulty valve on the well head. The preliminary report indicates the release measures 25' x 40' on location. Recovery amounts are unknown at this time. The release is located in Section 27, T23S, R29E in Eddy County, NM. Driving directions: FROM CARLSBAD GO TOWARD LOVING ON 285, TURN LEFT ON HWY 31, TURN RIGHT ON HWY 128, TURN RIGHT ON RAWHIDE ROAD GO TO END OF PAVEMENT, TURN RIGHT ON LEASE ROAD GO 3.5 MILES GO STRAIGHT 1.5 MILES, TURN EAST/LEFT ON MINOR LEASE ROAD, WELL IS .25 MILE STRAIGHT AHEAD GPS coordinates: N 32.27536 W 103.97690 API# 30-015-36137

Kathy Purvis

BBC International, Inc. 1324 W. Marland Blvd. Hobbs, NM 88240 Business: (575) 397-6388

Cell: (575) 441-8619

kathy@bbcinternational.com