NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

NOV 1 6 2016

Form C-141 Revised August 8, 2011

Subrech Company of Subrech Sub

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505

Santa Fe, NM 87303													
Release Notification and Corrective Action													
NAB 1432 638243						OPERATOR				X Ir	nitial Report	Final Report	
Name of Company: Burnett Oil Co., Inc. 3080							Contact: Johnny Titsworth						
							Telephone No. (432) 425-2891						
Facility Name: Jackson A 22							Facility Type: Well						
Surface Owner: BLM Mineral Owner: E							3LM				API No. 30-015-32066		
LOCATION OF RELEASE													
Unit Letter	Section	Township	Range	Feet from the		South Line	Feet from the		East/West Line		County		
J	13	17S	30E.	1650	FSL		1650		FEL		Eddy		
T. II. 1. 20 2020													
Latitude: 32.83173 Longitude: -103.92233													
Type of Release: PW/Oil Volume of Release: 4 oil/8 pw Volume Recovered: 3 oil/6 pw													
Type of Release: PW/Oil Source of Release: flowline						Date and Hour of Occurrence:				Date and Hour of Discovery			
						11/16/16			11/16/16 11:00				
Was Immediate Notice Given? X Yes ☐ No ☐ Not Required						If YES, To Whom? OCD - H. Patterson BLM - S. Tucker							
By Whom? Johnny Titsworth						Date and Hour: 11/16/16 1:15 pm							
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.						
☐ Yes X No													
If a Watercourse was Impacted, Describe Fully.*													
N/A													
Describe Cau	Describe Cause of Problem and Remedial Action Taken.*												
flowline coming off well head released approx. 12 bbls of total fluid. All standing fluid has been picked up and the line will be repaired.													
Describe Area Affected and Cleanup Action Taken.*													
					ea in the	pasture on t	ne North si	de of th	he locati	on. The a	rea will be reme	diated to	
release impacted a 30'x20' area on the well pad, and a 15'x30' area in the pasture on the North side of the location. The area will be remediated to regulatory standards.													
I hereby cert	ify that the	information g	iven abov	e is true and comp	ol e te to t	he best of my	knowledg	ge and u	ındersta	nd that pur	suant to NMOC	D rules and	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger													
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other													
federal, state, or local laws and/or regulations.													
				_		OIL CONSERVATION DIVISION							
Signature:							الأراكات						
Printed Name: Johnny Titsworth							Approved by Environmental Branch State of the Approved by Environmental Branch State of the Approved Branch State of the Approved by Environmental Branch State						
							Approval Date: 11 2 16 Expiration Date: NA						
Time. TISE	Coordinato	<u> </u>				, things Do			11-1	Pyhianon	· uv. 1 V//		

Conditions of Approval:

* Attach Additional Sheets If Necessary

Date: 11/16/16

E-mail Address: jtitsworth@burnettoil.com

Phone: (432) 425-2891

JRP 3499

Attached 🖫

Bratcher, Mike, EMNRD

From: Johnny Titsworth < jtitsworth@burnettoil.com>

Sent: Wednesday, November 16, 2016 1:23 PM

To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Tucker, Shelly

Cc: Kyle Adams; Leslie Garvis

Subject: Jackson A 22

Attachments: JA 22 initial C-141.pdf

All,

We had a release at the Jackson A 22 the standing fluid has been picked. The line is being repaired to put the well back into service. If there are any questions or concerns, feel free to contact us.

Johnny TitsworthHSE COORDINATOR

BURNETT OIL CO., INC.

P.O. Box 188 CR 220 North

Loco Hills, NM 88255 MOBILE: (432)-425-2891

EMAIL: jtitsworth@burnettoil.com

This message is intended only for the person(s) to which it is addressed and may contain privileged, confidential and/or insider information. If you have received this communication in error, please notify us immediately by replying to the message and deleting it from your computer. Any disclosure, copying, distribution, or the taking of any action concerning the contents of this message and any attachment(s) by anyone other than the named recipient(s) is strictly prohibited.