Received 6/25/2014

1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

NMOCD Dist 2 State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action NAB 1700 W52208 **OPERATOR** ☐ Initial Report Final Report Name of Company **OGRID Number** Contact Yates Petroleum Corporation 25575 Robert Asher Address Telephone No. 104 S. 4TH Street 575-748-1471 **Facility Name** API Number Facility Type Flora AKF State #4 30-015-32028 **Pumping Unit** Surface Owner Mineral Owner Lease No. State State VO-2597 LOCATION OF RELEASE Unit Letter Feet from the North/South Line Feet from the East/West Line Section Township Range County M 2 **22S** 31E 990 South 330 West Eddy Latitude 32.41582 Longitude 103.75554 NATURE OF RELEASE Type of Release Volume of Release Volume Recovered 2 B/O & 3 B/PW Crude Oil & Produced Water 0 B/O & 0 B/PW Source of Release Date and Hour of Occurrence Date and Hour of Discovery Poly Flow Line 6/5/2014, AM 6/5/2014, AM Was Immediate Notice Given? If YES, To Whom? ☐ Yes ☐ No ☒ Not Required By Whom? Date and Hour N/A N/A If YES, Volume Impacting the Watercourse. Was a Watercourse Reached? ☐ Yes ☒ No If a Watercourse was Impacted, Describe Fully. Describe Cause of Problem and Remedial Action Taken.* Poly flow line developed a leak. Isolated line, shut down well(s), called vacuum truck and crew to repaired line. Describe Area Affected and Cleanup Action Taken.* An approximate area of 35' X 25'. No oil or produced water to recover. The impacted area was brush hog mowed and Micro Blaze applied. Depth to Ground Water: >100' (approx. 125'), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Based on described clean-up actions and small amounts released, Yates Petroleum Corporation requests closure. 1 hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Approved by District Supervisor Printed Name: Robert Asher Expiration Date: NIA Title: NM Environmental Regulatory Supervisor Approval Date: Conditions of Approval: E-mail Address: boba@yatespetroleum.com Attached

2RP-

Phone: 575-748-4217

Date: Wednesday, June 25, 2014

Bratcher, Mike, EMNRD

From: Tanna Adams <TCAdams@yatespetroleum.com>

Sent: Wednesday, June 25, 2014 2:26 PM

To: Bratcher, Mike, EMNRD

Cc: Bob Asher

Subject:Flora AKF State #4Attachments:Flora AKF State.pdf

Follow Up Flag: Follow up Flag Status: Completed

Mr. Bratcher,

Please find attached the signed C141 Initial/Final for the below listed location:

Flora AKF State #4 30-015-32028 Section 2, T22S-R31E 990' FSL & 330' FWL Eddy County, New Mexico

Thank you,

Tanna Adams

Yates Petroleum Corporation Environmental Tech Environmental Department TCAdams@yatespetroleum.com

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.