

Received 8/6/2014

NMOCD Dist 2

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 S. First St., Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural ResourcesOil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505Form C-141  
Revised August 8, 2011Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

NAB 1700 L154U51

## OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	Contact Robert Asher
Address 104 S. 4 <sup>th</sup> Street	Telephone No. 575-748-1471
Facility Name Jacque AQJ State #7	Facility Type Well Pad

Surface Owner State	Mineral Owner State	API No. 30-015-33335
------------------------	------------------------	-------------------------

## LOCATION OF RELEASE

Unit Letter C	Section 34	Township 21S	Range 31E	Feet from the 990	North/South Line North	Feet from the 1650	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.43937 Longitude 103.76845

## NATURE OF RELEASE

Type of Release Crude Oil & Produced Water	Volume of Release 2 B/O & 8 B/PW	Volume Recovered 0 B/O & 0 B/PW
Source of Release Poly flow line	Date and Hour of Occurrence 7/23/2014; PM	Date and Hour of Discovery 7/23/2014; PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

There was a leak in the flow line, causing the release. Well was shut off; called vacuum truck and crew to repair line.

Describe Area Affected and Cleanup Action Taken.\*

An approximate area of 30 X 20' all on the well pad. Poly line was repaired and backhoe and roustabout crews were called to scape impacted soils from the pad area, those soils were taken to an NMOCD approved facility. **Depth to Ground Water: >100' (approximately 175', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 0. Based on minor amounts released, site ranking of zero and impacted soils scaped/hailed, Yates Petroleum Corporation requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

## OIL CONSERVATION DIVISION

Signature:



Printed Name: Robert Asher

Signed By   
Approved by Environmental Specialist:

Title: NM Environmental Regulatory Supervisor

Approval Date: 11/6/17

Expiration Date: N/A

E-mail Address: boba@yatespetroleum.com

Conditions of Approval:

FINAL

Attached ☐

Date: July 24, 2014

Phone: 575-748-4217

2RP-

\* Attach Additional Sheets If Necessary

2RP-4043

**Bratcher, Mike, EMNRD**

---

**From:** Tanna Adams <TCArms@yatespetroleum.com>  
**Sent:** Wednesday, August 6, 2014 9:12 AM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Patterson, Heather, EMNRD; Bob Asher  
**Subject:** Jacque AQJ State #7  
**Attachments:** Jacque 7.pdf

**Follow Up Flag:** Follow up  
**Flag Status:** Completed

Mr. Bratcher,

Please find attached the signed C141 Initial/Final report for the below listed location:

**Jacque AQJ State #7**  
**30-015-33335**  
**Section 34, T21S-31E**  
**990' FNL & 1650' FWL**  
**Eddy County, New Mexico**

Thank you,

*Tanna Adams*  
Yates Petroleum Corporation  
Environmental Tech  
Environmental Department  
TCArms@yatespetroleum.com

---

**This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.**

---