

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

FEB 23 2017

Submit 1 Copy to appropriate District Office
accordance with 19.15.29 NMA

RECEIVED

Form C-14
Revised August 8, 20

FAB1706050826 Release Notification and Corrective Action

NAB1706050988

OPERATOR

Initial Report Final Report

Name of Company DCP 227828	Contact Haskell Conder
Address 10 Desta Drive, Suite 400 West	Telephone No. cell 432-557-1127
Facility Name SC-1-13-1 Line Leak	Facility Type Natural Gas Gathering Pipeline
Surface Owner Bounds	Mineral Owner
API No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	27	24S	24E					Lea

Latitude: 32.18938 Longitude : -104.28916

NATURE OF RELEASE

Type of Release: possible natural gas	Volume of Release	Volume Recovered
Source of Release pipeline	Date and Hour of Occurrence Unknown / Historical	Date and Hour of Discovery Unknown / Historical
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* N / A

Describe Cause of Problem and Remedial Action Taken.*

Received report of disturbed area on DCP pipeline ROW from land owner on February 2nd, 2017. DCP will delineate site and if warranted will submit remediation plan.

Describe Area Affected and Cleanup Action Taken.*

Plat of disturbed area and delineation results will be submitted to NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Haskell Conder</i>	Approved by Environmental Specialist: Signed By: <i>[Signature]</i>	
Printed Name: Haskell Conder	Approval Date: 3/1/17	Expiration Date: N/A
Title: Compliance Coordinator	Conditions of Approval:	
E-mail Address: hconder@dcpmidstream.com	Attached <input type="checkbox"/>	
Date: 02/23/17	Phone: 432-557-1127	

* Attach Additional Sheets If Necessary

2RP-4131

Bratcher, Mike, EMNRD

From: Conder, Haskell P <HPConder@dcpmidstream.com>
Sent: Thursday, February 23, 2017 1:20 PM
To: Bratcher, Mike, EMNRD
Cc: Weaver, Crystal, EMNRD; Blair, Yvonne B
Subject: FW: SC-1-13-1 C141.doc
Attachments: SC-1-13-1 C141.doc

Mr. Bratcher, Attached is the C-141 for the SC-1-13-1 site . If you have questions or concerns please contact me.

Hack Conder
Compliance Coordinator
DCP Midstream, LP
1625 W. Marland
Hobbs, NM 88240
(432) 557- 1127 mobile
(575) 397-5584 office
(575) 397-5598 fax