

**NM OIL CONSERVATION
ARTESIA DISTRICT**

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

MAY 26 2017

Form C-141
Revised August 8, 2011

RECEIVED Copy to appropriate District Office in accordance with 19.15.29 NMAC.

LAB1715048102
NAB1715048310

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: ETC Field Services <i>371123</i>	Contact: Johnnie Bradford
Address: 600 N. Marienfeld Street, Ste. 700	Telephone No. (432) 250-5542 (cell) (817) 302-9812 (off)
Facility Name: Barn Owl (Trunk H 10")	Facility Type: Pipeline

Surface Owner:	Mineral Owner:	API No.
----------------	----------------	---------

LOCATION OF RELEASE

Unit Letter C	Section 18	Township 26S	Range 37E	Feet from the 384.87	North/South Line South	Feet from the 30.93	East/West Line East	County Lea County
-------------------------	----------------------	------------------------	---------------------	--------------------------------	----------------------------------	-------------------------------	-------------------------------	-----------------------------

Latitude 32.04795N Longitude 103.202W

NATURE OF RELEASE

Type of Release: Gas Only	Volume of Release: 223.341 Mscf	Volume Recovered: N/A
Source of Release: Gathering System Pipeline	Date and Hour of Occurrence: 04/19/2017 15:30	Date and Hour of Discovery: 04/19/2017 15:30
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? : N/A	
By Whom? N/A	Date and Hour: N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. A Watercourse was not impacted during this event.	

If a Watercourse was Impacted, Describe Fully.*

This was a gas only release; therefore, no watercourse was impacted.

Describe Cause of Problem and Remedial Action Taken.*

Pipeline was blown down to facilitate a flow meter connection into the gathering system. There was no liquid associated with this venting of the pipeline.

Describe Area Affected and Cleanup Action Taken.*

None Needed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Johnnie Bradford</i>	OIL CONSERVATION DIVISION	
Printed Name: Johnnie Bradford	Approved by <i>[Signature]</i> Environmental Specialist	
Title: Sr. Environmental Specialist	Approval Date: 5/20/17	Expiration Date: N/A
E-mail Address: johnnie.bradford@energytransfer.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 05/26/2017 Phone: (432) 250-5542		

* Attach Additional Sheets If Necessary

2RP-4232

Bratcher, Mike, EMNRD

From: Bradford, Johnnie <Johnnie.Bradford@energytransfer.com>
Sent: Friday, May 26, 2017 8:59 AM
To: Bratcher, Mike, EMNRD
Subject: C-141 Submittal - Energy Transfer Field Services
Attachments: eddy.pdf

Good morning Mike,

Due to recent personnel changes and miscommunication on my part, I am submitting these two C-141 Forms for "Gas Only" releases which occurred on Energy Transfer properties. There were no impacts to soil from liquids associated with these gathering system pipeline leaks. If you should have any questions, please don't hesitate to give me a call.

Sincerely,

Johnnie



Johnnie Bradford | Sr. Environmental Specialist
600 N. Marienfeld Suite 700; Midland, TX 79701
O: 817.302.9812 | M: 432.250.5542
johnnie.bradford@energytransfer.com

Private and confidential as detailed [here](#). If you cannot access hyperlink, please e-mail sender.