

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised March 17, 1999

Oil Conservation Division
2040 South Pacheco
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Conoco, Inc.	Contact Ken Anderson
Address 10 Desta Drive, Suite 100W, Midland, TX 79705-4500	Telephone No. (505) 390-4821
Facility Name WUSA #138	Facility Type Oil and Gas Well <i>30025 33857 0000</i>


Surface Owner State of New Mexico	Mineral Owner BLM	Lease No. LC#031695B
--------------------------------------	----------------------	-------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	27	20S	38E	1980	FSL	660	FWL	LEA

NATURE OF RELEASE

Type of Release Oil and Salt Water	Volume of Release 3 bbls of Oil and 5 bbls of Salt Water	Volume Recovered 3 bbls of Oil and 5 bbls of Salt Water
Source of Release <i>Internal Corrosion of pipeline</i>	Date and Hour of Occurrence 10/28/02 at 6:00 AM	Date and Hour of Discovery 10/28/02 at 9:15 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Cause of Problem: Internal Corrosion Remedial Action Taken: The line will be replaced. An emergency clamp was installed on the line		
Describe Area Affected and Cleanup Action Taken.* Area Affected: Spill covered an area approximately 30'x 50'. Cleanup Action Taken: Skimmed oil off rainwater with a vacuum truck. The soil will be remediate in place.		



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases, which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Betsy Ritter</i>	OIL CONSERVATION DIVISION	
Printed Name: Betsy Ritter	Approved by District Supervisor:	
Title: Agent for Conoco	Approval Date:	Expiration Date:
Date: November 1, 2002 Phone: (915) 570-6007	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary
Conoco Phillips 217817
incident - nPAC 0610048300
application - nPAC 0610048556

02-200