NM OIL CONSERVATION

1625 N. French Dr., Hobbs, NM 8824NRTESIA DISTRICT

SEP 1 1 2017 811 S. First St., Artesia, NM 88210

District I

District III
1000 Rio Brazos Road, Aztec, NM 874 District IV 1220 S. St. Francis Dr., Santa Fe, NM 8 RECEIVED State of New Mexico NM OIL CONSERVATION

Energy Minerals and Natural Resources ARTESIA DISTRICT

Revised August 8, 2011 Simular Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141

BECEIVED

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe NM 87505

Release Notification and Corrective Action												
NAB 1725730519						OPERAT				al Report	\boxtimes	Final Report
Name of Company Devon Energy Production Company 6/31												
Address 6488 Seven Rivers Hwy Artesia, NM 88210						Telephone No. 575-390-5436						
Facility Name Serene Sisters 25 Fed 2H						Facility Type Oil						
Surface Owner Federal Mineral Owner						r Federal API No 30-015-38313						
				LOCA	TION	OF REI	LEASE					
Unit Letter	Section	Township	Range	Feet from the		th/South Line Feet from the East/West Line County						
Α	25	18S	31E	267]	FNL 1002 FEL EDDY						
Latitude: 32.7251205 Longitude: -103.8176651												
e e e e e e e e e e e e e e e e e e e												
Type of Release Oil Volume of Release 10 bbls Oil Volume Recovered 10 bbls Oil												
Source of Release Oil storage tank										d Hour of Discovery		
						8/2/2017 1:30 PM 8/2/2017 1:30 PM						
Was Immediate Notice Given? ⊠ Yes □ No □ Not Required						If YES, To Whom? BLM- Shelly Tücker & OCD-Olivia Yu						
By Whom? Wesley Ryan-Production Foreman						Date and Hour BLM: August 3, 2017 1:00 PM OCD: August 3, 2017 1:10 PM						
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse N/A						
If a Watercourse was Impacted, Describe Fully. N/A												
Describe Cause of Problem and Remedial Action Taken. Oil storage tank had a hole on the bottom of the tank resulting in the release. Upon discovery the production was switched into a different tank. The tank was then emptied.												
Describe Area Affected and Cleanup Action Taken. 10 BBLS of Oil was released from the storage tank. The release originated at the bottom of the storage tank where a hole developed. All released fluids remained inside the lined SPCC containment. A vacuum truck was dispatched and 10 BBLS of Oil were recovered. Once fluids were removed the liner was visually inspected by Devon field staff for any pinholes or punctures and none were found. Based on this inspection there is no evidence that the spill fluids left the lined containment.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
Signature: Jennífer Reyna						OIL CONSERVATION DIVISION						
Printed Name: Jennifer Reyna						Approved by Environmental Specialist: White Washington						
Title: Field Admin Support						Approval Date: 9/14/17 Expiration Date: NIA						
E-mail Addre	ess: jennife r	r.reyna@dvn	.com			Conditions of	f Approval: FIN	101	_	Attached	M	4.05.4
Date: 8/	7/17	Phon	e: 575.746	5.5588			FIN	IHL		1	3KP	'-438 4

aludinas

^{*} Attach Additional Sheets If Necessary

Weaver, Crystal, EMNRD

From: Reyna, Jennifer < Jennifer.Reyna@dvn.com>

Sent: Friday, August 11, 2017 2:53 PM

To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; Shelly Tucker (stucker@blm.gov)

Cc: Ryan, Wesley; Aguilar, Leonard; Fulks, Brett; Shoemaker, Mike

Subject: Serene Sisters 25 Fed 2H_10 bbl oil_8-2-17

Attachments: Serene Sisters 25 Fed 2H_10 bbl oil_8-2-17 GIS Image.pdf; Serene Sisters 25 Fed 2H_10

bbl oil_8-2-17 intial C-141.doc

Good Afternoon,

Attached please find the Initial C-141 and GIS Image for 10 bbls of oil release at the Serene Sisters 25 Fed 2H on 8.2.17.

If you have any questions please feel free to contact me.

Thank you,

Jennifer Reyna

Field Admin Support Production B-Schedule

Devon Energy Corporation P.O. Box 250 Artesia, NM 88211 575 746 5588



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.