ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

JAN 1 2 2018

OIL CONSERVATION D

Expiration Date:

Approved by Environmental Specialist:

Form C-141 Revised April 3, 2017

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in RECEIVED NMAC.

FAB 180 45444 **Release Notification and Corrective Action** NAB 1801 656623 **OPERATOR** ☐ Initial Report Final Report Enterprise Field Services, LLC | 60034 / Contact Name of Company Alena Miro PO Box 4324, Houston, TX 77210 Address Telephone No. 575-628-6802 **Facility Name** Pipeline ROW, Trunk B Facility Type Natural Gas Pipeline Surface Owner BLMMineral Owner N/A API No. N/A LOCATION OF RELEASE Unit Letter North/South Unit Line East/West Line Section Township Range Feet from the Feet from the County 235 31E South East Eddy Latitude _N32.273103 Longitude W-103.797123 NAD83 NATURE OF RELEASE Type of Release Natural Gas Volume of Release 103 MCF Volume Recovered N/A Source of Release Blowdown vent Date and Hour of Occurrence Date and Hour of Discovery 1/10/2018 1/10/2018 Was Immediate Notice Given? If YES, To Whom? ☐ Yes ☒ No ☐ Not Required By Whom? Date and Hour Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ☐ Yes ☒ No If a Watercourse was Impacted, Describe Fully.* NA Describe Cause of Problem and Remedial Action Taken.* Natural gas blow down was due to a line freeze. Pipeline segment was isolated, blown down, and serviced. Describe Area Affected and Cleanup Action Taken.* I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health

or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other

713-381-6684

Approval Date:

Conditions of Approval:

Date: 1/1/2018 Phone:
Attach Additional Sheets If Necessary

federal, state, or local laws and/or regulations.

Jon E. Fields

jefields@eprod.com

Director, Field Environmental

Signature:

Title:

Printed Name:

E-mail Address:

Weaver, Crystal, EMNRD

From: Mendez, Brenda <BJMendez@eprod.com>

Sent: Friday, January 12, 2018 6:59 AM

To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; 'yjordan@blm.gov'

Cc: Reinermann, Paul; Nolan, Shiver

Subject: Trunk B - C-141

Attachments: Eddy County C-141 Release Report Trunk B (1-10) January 2018.pdf

Attached is the C-141 Report form for Trunk B in Eddy County, NM. Should you need additional information, please contact Mr. Paul Reinermann at 210-528-2184.

Thank you Brenda J. Mendez – Planning and Reports Analyst Enterprise Products Operating, LLC Tel (713) 381-8270 – Fax (713) 880-6660 bjmendez@eprod.com

This message (including any attachments) is confidential and intended for a specific individual and purpose. If you are not the intended recipient, please notify the sender immediately and delete this message.