

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OCD received
on 2/9/18
District II

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB18101057965

OPERATOR

X Initial Report Final Report

Name of Company Vanguard Operating, LLC <i>258350</i>	Contact Jason Fisher
Address 5847 San Felipe, STE 3000 Houston, TX 77057	Telephone No. 505-918-0523
Facility Name Marathon 26 State Battery	Facility Type Tank Battery
Surface Owner	Mineral Owner State
API No. 3001529413	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	26	17S	28E	990	North	2310	East	Eddy

Latitude_32.8106842_ Longitude_-104.1459503 NAD83

NATURE OF RELEASE *X2 = 200MCF*

Type of Release Gas/Emissions	Volume of Release 100 MCFD	Volume Recovered 0
Source of Release Flare	Date and Hour of Occurrence 2-3-2018	Date and Hour of Discovery N/A
Was Immediate Notice Given? X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Amalia Bustamante by email	
By Whom? Chuck Johnston	Date and Hour 7:30 pm 2-3-2018	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

Purchaser found leak on their pipeline and requested a volume reduction while making repairs. Gas was sent to flare for two days.

Describe Area Affected and Cleanup Action Taken.*

No impact.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Chuck Johnston

Printed Name: Chuck Johnston

Approved by Environmental Specialist:

Accepted for record

Title: EHS Specialist

Approval Date: *4/12/18*

Expiration Date: *N/A*

E-mail Address: cjohnston@vnrenergy.com

Conditions of Approval:

Final

Attached

APP-4701

Date: 2-9-2018

Phone: 432-202-4771

* Attach Additional Sheets If Necessary

4/12/18 AB

Weaver, Crystal, EMNRD

From: Chuck Johnston <cjohnston@vnrenergy.com>
Sent: Friday, February 9, 2018 9:25 AM
To: Weaver, Crystal, EMNRD; Bratcher, Mike, EMNRD
Subject: Weekend Flaring
Attachments: 2018-02-09 Flare.pdf

Crystal and Mike, please find attached the C-141's for flaring from 8 of our batteries over the weekend. Please let me know if you need anything else.

Chuck Johnston
EHS / Operations Specialist
432-202-4771 Cell
432-248-8154 Office



Bustamante, Amalia, EMNRD

From: Chuck Johnston <cjohnston@vnrenergy.com>
Sent: Saturday, February 3, 2018 7:41 PM
To: Bustamante, Amalia, EMNRD
Subject: Flaring

Amalia, I just got word we are having to flare on a few batteries due to a pipeline leak on our purchaser's line. I will complete the C-129s when I get back to the office Tuesday.

Thanks

Chuck Johnston
EHS / Operations Specialist
432-202-4771 Cell
432-248-8154 Office