

7057232

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company CHEVRON USA INC.	Contact Larry Williams
Address P.O. Box 1949 Eunice NM. 88231	Telephone No. 505-394-1237 (office), 505-390-7165 (cell)
Facility Name- H T Mattern D 8	Facility Type - flow line

Surface Owner- State of New Mexico	Mineral Owner - State of New Mexico	Lease No. 01770800
------------------------------------	-------------------------------------	--------------------

LOCATION OF RELEASE


AP1# 30025247640000

Unit Letter E	Section 6	Township 22S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude 32 42.5 Longitude 103 21.2

NATURE OF RELEASE

Type of Release-OIL AND PRODUCED WATER	Volume of Release 1 BO, 7 BW	Volume Released 0
Source of Release- 2 1/2" STEEL FLOWLINE	Date and Hour of Occurrence- 5/10/06	Date and Hour of Discovery 5/10/06 @ 1:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Caperton	
By Whom? Larry Williams	Date and Hour 5/11/06 @ 1:00 P.M.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* EXTERNAL CORROSION ON STEEL FLOWLINE THAT WAS BURIED. REPLACE FLOWLINE

Describe Area Affected and Cleanup Action Taken.* FLUID IMPACTED AND AREA OF 20' X 30' ALONG SIDE OF FLOWLINE IN PASTURE. WILL PICK UP HYDROCARBON IMPACTED SOILD AND CARRY TO LAND FARM

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Larry Williams</i>	OIL CONSERVATION DIVISION	
Printed Name: Larry Williams	Approved by District Supervisor:	
Title: HES Champion	Approval Date:	Expiration Date:
E-mail Address: lcwl@chevrontexaco.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 5/11/06 Phone: 505-394-1237		

* Attach Additional Sheets If Necessary

*incident - nPAC0613226759
application - nPAC0613227418*