District I 1625 N. French Dr., Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

т. т

Release Notification and Corrective Action  OPERATOR  Initial Report  Final Report														
Name of Company Chevron USA Inc.									Initia	al Report		Final	Report	
				1 88260	Contact Wayne Minchew Telephone No. 505-396-4414									
							Facility Type Water Injection Station							
Surface Owner Mineral Owner														
Surface Ow	ner			Mineral	)wner	Lease No. Pump #2, Sat. #1								
	,		P**1	·		N OF REI							······································	
Unit Letter	Section	Township	Range	Feet from the	North/	South Line	Feet from the	East/W	est Line	County				
В	36	17S	34E							Lea				
Latitude Longitude														
NATURE OF RELEASE														
Type of Rele					Volume of Release 8 bbls Volume Recovered 2bbls									
Source of Release suction piping							Date and Hour of Occurrence O5-31-06 3:30 pm Date and Hour of Discovery O5-31-06 3:30							
Was Immediate Notice Given?							If YES, To Whom?							
Yes No Not Required														
By Whom? Larry Ridenour Was a Watercourse Reached?							Date and Hour 06-01-06 7:46am  If YES, Volume Impacting the Watercourse.							
			Yes 🗵	No										
If a Watercou	ırse was Im	pacted, Descr	ibe Fully.	*								•		
Describe Cau	se of Probl	em and Reme	dial Actio	n Taken.*				<u> </u>		5031	33 d	7		
Describe Cause of Problem and Remedial Action Taken.*  External Corrosion, line was shut in until able to patch. Piping section will be replaced with stainless steel.  Describe Area Affected and Cleanup Action Taken.*														
Describe Area Affected and Cleanup Action Taken.*												ired Pad		
Describe Area Affected and Cleanup Action Taken.*  20x40 area inside battery yard, vacuum truck picked up what water remained on surface.														
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.														
N							OIL CONSERVATION DIVISION A							
Signature: P. W. Muel:									BAB !					
						Approved by	District Supervis	sor: 🙇	May Wenty					
							pproval Date: 6-17-01 EXPIRATION DERITAL ENGINEER						Ì	
							Conditions of Approval:			EMAIN QUARTER				
										Attached [				
Attach Addi	tional Shee	ets If Necess	ary i	. 505-570-4414				<u> </u>						
Attach Addi Laculd Chaile Cipplic	w FP tak-n	1AC 0610 1 PAC 06 - 0PAC 0	\$407 1454 16145	164 0836 541034										
Whiten	uum	· [ - ·	•	. 0/										