

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company BP Pipelines (NA) Inc	Contact Jimmy Humble
Address 502 N. West Ave. Levelland, Texas	Telephone No. 505-396-9922
Facility Name Maljamar Gathering Pipeline	Facility Type Pipeline

Surface Owner ROSS CAVINESS	Mineral Owner	Lease No.
-----------------------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter SW 4 NE 4	Section 31	Township T17S	R33E	Feet from the	North/South Line	Feet from the	East/West Line	County LEA
-----------------------------	---------------	------------------	------	---------------	------------------	---------------	----------------	------------

Latitude N 32 47.677 Longitude W 103 41.818

NATURE OF RELEASE

Type of Release : Crude Oil Spill	Volume of Release: >25 bbl	Volume Recovered 0
Source of Release: Pipeline	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery 7-10-06 13:10 Hours
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? PAT Telephone 393-6161	
By Whom? Jimmy Humble	Date and Hour 7/11/06 10:30 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Corrosion caused pipe to fail resulting in spill.

Describe Area Affected and Cleanup Action Taken.*

Surface area is approximately 15' X 30' Depth is being determined. Soils will be Remediation is being undertaken by environmental consultant.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Jimmy Humble	Approved by District Supervisor:		
Title: Lovington Core Team Leader	Approval Date:	Expiration Date:	
E-mail Address: Jimmy.Humble@bp.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 7/12/06	Phone: 505-396-9922		

* Attach Additional Sheets If Necessary

Facility - FPAC 0619930362
Incident - NPAC 0619930448

Application - FPAC 0619930768
RP# 956