


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Chesapeake Energy	Contact: Bradley Blevins
Address: 5014 Carlsbad Highway	Telephone No.: (505) 391-1462 ext. 24
Facility Name: Newman 32 State Well #2	Facility Type: Oil Well

Surface Owner: State of New Mexico	Mineral Owner: State of New Mexico	Lease No.: A0-2614-0000
------------------------------------	------------------------------------	-------------------------

LOCATION OF RELEASE *API# 3002537170 0000*

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	32	<i>22S</i> <i>23S</i>	38E	660	North	2,310	East	Lea

Latitude: N 32° 15' 58.57" Longitude: W 103° 04' 53.54"

NATURE OF RELEASE

Type of Release: Oil and Water	Volume of Release: 70 barrels	Volume Recovered: 25 barrels
Source of Release: Oil Well	Date and Hour of Occurrence: 24 October 2005	Date and Hour of Discovery: 25 October 2005 early am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Gary Wink NMOCD	
By Whom? Iain Olness	Date and Hour: 25 October 2005 @ 1040 hrs	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	

If a Watercourse was Impacted, Describe Fully.* Not Applicable

Describe Cause of Problem and Remedial Action Taken.* Stuffing box on pumping unit blew out. Stuffing box was repacked and bolts replaced.

Describe Area Affected and Cleanup Action Taken.* Approximately 5,600 square feet of surface area was impacted by the release. A vacuum truck was retained to recover product. Saturated soil is being excavated and stockpiled on plastic. The site will be delineated and a Remediation/Closure Plan developed and submitted to the NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins		Approved by District Supervisor:	
Title: Field Supervisor	Approval Date:	Expiration Date:	
E-mail Address: bblevins@chkenenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date:	Phone: (505) 391-1462 ext. 24		

* Attach Additional Sheets If Necessary

Incident - nPAC0622747229
Application - nPAC0622747346

RP# 1002