

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR x Initial Report Final Report

Name of Company Plains Marketing, LP	Contact Camille Reynolds
Address 3112 West US Hwy. 82, Lovington, NM	Telephone No. 505-441-0965
Facility Name Covington A Federal #1 Sump	Facility Type Station

Surface Owner BLM	Mineral Owner	Lease No.
-------------------	---------------	-----------


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	25	22S	32E					Lea

Latitude 32°22'40.0" Longitude 103°37'49.0"

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 10 barrels	Volume Recovered 5 barrels
Source of Release Sump valve on pump	Date and Hour of Occurrence 8/18/2006 @ 11:15	Date and Hour of Discovery 8/18/2006 @ 11:30
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Caperton	
By Whom? Camille Reynolds	Date and Hour 8/18/2006 @ 15:45	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.*
400+

Describe Cause of Problem and Remedial Action Taken.* Sump valve on pump vibrated open. The valve was closed to mitigate the release. The pressure on the line is approximately 20 psi and the gravity of the sweet crude oil is 41. The oil has an H2S content of <10 ppm. This was a surface release.

Describe Area Affected and Cleanup Action Taken.* The impacted soil was excavated and stockpiled on plastic. Aerial extent of surface impact was 1,450 square feet.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Camille Reynolds</i>	OIL CONSERVATION DIVISION	
Printed Name: Camille Reynolds	Approved by District Supervisor:	
Title: Remediation Coordinator	Approval Date:	Expiration Date:
E-mail Address: cjreynolds@paalp.com	Conditions of Approval:	
Date: <i>8/22/2006</i> Phone: 505-441-0965	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

*facility - PPAC0623749244
incident - PPAC0623749373
application - PPAC0623749483*

RP# 1008