

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Rice Operating Company	Contact: Jennifer Johnson
Address: 122 West Taylor	Telephone No.: 505-393-9174
Facility Name: BD	Facility Type: Salt Water Gathering System

Surface Owner: Delrose Scott	Mineral Owner:	Lease No.:
------------------------------	----------------	------------

LOCATION OF RELEASE

Unit Letter K	Section 23	Township 21S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude: 32°27.847N Longitude: 103°08.004W

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 11 barrels	Volume Recovered:
Source of Release: Poly pipeline	Date and Hour of Occurrence: 8/15/06 10:00 am	Date and Hour of Discovery: 8/15/06 10:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse:	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* During routine line maintenance a Poly valve broke off of a flange adapter. Rice Operating Company (ROC) personnel replaced the valve with a lugbody valve.

Describe Area Affected and Cleanup Action Taken.* Approximately 744 sq ft were affected. ROC personnel were on site when the accidental discharge occurred. Immediate action was taken using vacuum trucks to remove produced water from the junction box. The 744 sq ft area will be scraped to a depth not to exceed 4". The site will be seeded at a later date. Because of immediate corrective action vertical penetration at this site is minimal, therefore there is no threat to groundwater. ROC is requesting closure with this final C-141.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jennifer A Johnson</i>		OIL CONSERVATION DIVISION	
Printed Name: Jennifer Johnson		Approved by District Supervisor: <i>[Signature]</i>	
Title: Environmental and Field Technician		Approval Date: 8-28-06	Expiration Date: —
E-mail Address: jjohnson@riceswd.com		Conditions of Approval:	
Date: 8/18/06 Phone: 505-393-9174		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

Facility - PPAC0624348890
Incident - PPAC0624348973

application - PPAC0624349099
RPT# 1010

BD K-23 ACCIDENTAL DISCHARGE

DRIVING DIRECTIONS

GPS

NAD27

32°27.847N

103°08.004W

From the intersection of 234 (Andrews Hwy) and Hwy 18 to north on Hwy 18 1.7 miles. Turn west on Apache Road and go 0.4 miles. Turn north on the lease road and go approximately 0.1 miles, site is on the west side of the road.