

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Site # 70

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action


OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company: Targa Midstream Services, L.P.	Contact: Don Embrey or Cal Wrangham		
Address: PO Box 1909 Eunice, NM 88231	Telephone No.: (432) 688-0555		
Facility Name: Eunice Gathering System	Facility Type: Gas Gathering System		
Surface Owner: Clay Osborne	Mineral Owner	Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	35	21S	37E					

Latitude: N 32, 25'45" Longitude: W 103, 07'56.8"

NATURE OF RELEASE

Type of Release: Natural Gas Condensate	Volume of Release: Unknown	Volume Recovered: None
Source of Release: Pipeline Leak	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*		
Pipeline leak due to interior and exterior corrosion. Replaced pipeline and excavated impacted soil.		
Describe Area Affected and Cleanup Action Taken.*		
Some staining along pipeline right-of-way. Have excavated soil to NMOCD guidelines. Documentation found in attached report.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 		
Printed Name: Cal Wrangham		
Title: ES&H Advisor	Approval Date:	Expiration Date:
E-mail Address: cwrangham@targaresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4/20/06 Phone: (432) 688-0542		

* Attach Additional Sheets If Necessary

59'

Facility # PAC0627136134
Incident - n PAC0627136250
Application - p PAC0627136345

RP# 1048