

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: John H. Hendrix Corporation	Contact: Marvin Burrows
Address: 1310 16 th Street, Eunice, New Mexico 88231	Telephone No.: (505) 394-2649
Facility Name: Baker Tank Battery	Facility Type: Production Tank Battery (out-of-service)

Surface Owner: Irvin Boyd	Mineral Owner	Lease No.:
---------------------------	---------------	------------


LOCATION OF RELEASE

Unit Letter D	Section 26	Township 22S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County: Lea
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	-------------

53'

Latitude: North 32° 22' 01.4" Longitude: West 103° 08' 28.6"

NATURE OF RELEASE

Type of Release: Historical	Volume of Release: Unknown	Volume Recovered: Unknown
Source of Release: Tank Battery	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: Unknown
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Historic contamination around tank battery requires remediation per Buddy Hill inspection and NOV dated 08/15/2005. Remediation plan was approved by OCD on January 5, 2006.		
Describe Area Affected and Cleanup Action Taken.* Historic hydrocarbons from spills around tank and piping will be remediated per OCD approved work plan.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Mark J. Larson, Agent	Approved by District Supervisor:	
Title: Sr. Project Manager / President, Larson and Associates, Inc. (agent for John H. Hendrix Corporation)	Approval Date:	Expiration Date:
E-mail Address: mark@laenvironmental.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: October 6, 2006 Phone: (432) 687-0901		

* Attach Additional Sheets If Necessary

incident - n PAC0628352434
facility f PAC0628352288
application - p PAC0628352626 RP # 1071

