Form C-141

District I 1625 N. French Dr., Hohbs, NM 88240 District II 130) W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztoc, NM 87410 District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

Name of Company

State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revise 1 October 10, 2003

Submit 2 Cop es to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action **OPERATOR** OGRID Number | Contact

YATES PETROLEUM CORPORATION 25575						SHERRY BONHAM					
Address						Telephone No.					
105 S 4 TH STREET Facility Name API Number						505.748.1471 Facility Type					
MERLE STATE UNIT 3 30-025-37545						WELL					
Surface Own) A (1		_	Mineral O			Loa	sc No.			
STATE STATE					WIICI	Lease No.					
LOCATION OF RELEASE											
Unit Letter	Section Township		Range Feet from the					East/West Liv	ne C	ounty	
P	14	108	34E	990	SOUT	ГН	990	EAST	L	ĖΛ	
		(34?)	<u> </u>	Lutituda 22	44253	Longitude	107 42007	<u> </u>			
Type of Relea	960	:		NA.	Thk			Volve	ma Dan	Number	
CRUDE OIL						Volume of Release Volume Recover 10 B/O 8 B/O				JA6(6()	
Source of Release										ar of Discovery	
WATER TANK Was Immediate Notice Given?						10/4/06 7:00 AM 10/4/06 7:00 AM 1ΓΥΕS, Το Whom?					
☐ Yes ☐ No ☒ Not Required N/A											
By Whom?				· · · · · · · · · · · · · · · · · · ·		Date and H	our				
N/A Was a Watercourse Reached?						N/A If YES, Volume Impacting the Watercourse.					
,			Yes 🔯 1	No :		11 123, 40	mue mpacang an	, Municipie.			
If a Watercourse was Impacted, Describe Fully.*											
N/A		,		•							
•				:							
· · · · · · · · · · · · · · · · · · ·		<u> </u>									
Describe Cause of Problem and Remedial Action Taken.* WELL TESTER (3 PHASE SEPARATOR) MALEUNCTIONED PLITTING OIL PRODUCTION TO WATER TANK, PERAURED											
WELL TESTER (3 PHASE SEPARATOR) MALFUNCTIONED PUTTING OIL PRODUCTION TO WATER TANK. REPAIRED.											
						\$					
Describe Area Affected and Cleanup Action Taken.											
AN APPROXIMATE 25' X 25' X 2" AREA AFFECTED. PICKED UP ALL STANDING FLUIDS, IMMEDIATELY SCRAPED UP IMPACTED											
MATERIALS AND HAULED TO LAND FARM, SITE TO BE EVALUATED. SITE RANKING: 20											
	•										
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCI) rules and regulations											
all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public at alth or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have											
failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and or regulations.											
MAIOCD 466	ehemice of a C	-141 report a	oos not re	leve the operator p	10वृक्षका १०	isibility for cor					
OIL CONSERVATION DIVISION											
Signuture	XILLY X	-		-		ENORMAN					
Printed Name: Sherry Bonham						Approved by District Supervisor:					
Title: Environmental Regulatory Agent							Approval Date: 60.28-06 Expiration Date:				
E-mail Address: sherryb@ypcnm.com						Conditions of Approvals					
Date: Octob	er 18 2006	:	DL.	one: 505 748 147	,	Attached []				Attached []	

* Attach Additional Sheets If Necessary

rcident - nPACO629231875 plication - pPACO629232002