

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street	API Number 30-025-31889	Telephone No. 505-748-1471
Facility Name Kiwi AKX State #8	Facility Type Battery	
Surface Owner State	Mineral Owner State	Lease No. VB-134

LOCATION OF RELEASE

Unit Letter F	Section 16	Township 22S	Range 32E	Feet from the 1980	North/South Line North	Feet from the 2310	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.39337 Longitude 103.68028

NATURE OF RELEASE

Type of Release Crude Oil & Produced Water	Volume of Release 25 B/O & 150 B/PW	Volume Recovered 15 B/O & 80 B/PW
Source of Release Pump Hose	Date and Hour of Occurrence 12/8/2006 - AM	Date and Hour of Discovery 12/8/2006 - AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Caperton, OCD District I	
By Whom? Robert Asher, Environmental Regulatory Agent, YPC	Date and Hour 12/11/2006 (W) @ 11:40 AM & E/M @ 10:30 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Vibration on pump caused line to break at well head and bull plug on injection well came off. Pump shut down/valves closed, vacuum truck called. Hose replaced.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 50' X 100', contained on well pad and within bermed area. Well pad to be scraped and contaminated soil taken to an OCD approved land disposal facility. Depth to Ground Water: >100'; Wellhead Protection Area: No; Distance to Surface Water Body: >1000'; SITE RANKING IS 0.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature:	Approved by District Supervisor:	
Printed Name: Robert Asher	Approval Date: 12/19/06	Expiration Date: 2/20/07
Title: Environmental Regulatory Agent	Conditions of Approval: Submit workplan & begin remediation activities	
E-mail Address: boba@ypcnm.com	ATTACHED <input type="checkbox"/>	
Date: Thursday, December 14, 2006	Phone: 505-748-1471	

* Attach Additional Sheets If Necessary

incident - n PAC0635352121
application - p PAC0635352222

RP#1154